Certificate of Location of Government Corner

ID#: 733105 **Description:** SW SEC COR 31 73 **Date Set:** 10/24/1985 **County:** Olmsted

Section: 31 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 7' west of center line of concrete median north on 19th Ave SE and 20' south of back of curb at south end of median
The monument is at the surface
This corner is located by GPS measurement

Corner History:

9-30-1853 John Ball, Deputy Surveyor, measured north (Variation 9° 6' East) between sections 1 and 6, 80.00 chains and set post for corner to Townships 106 & 107 North of Ranges 13 & 14 West of 5th Prime Meridian. Built mound with trench per instructions. RP - 10" Burr Oak N60°W 387 links (255.42').

10-4-1853 John Ball, Deputy Surveyor, measured east on random line, between Townships 106 & 107 North of Range 14 West, 5 miles, 78 chains, 5 links. Intersected East Township line 58 links (38.28') south of township corner section post.

7-20 to 23-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy Surveyor, (Old Road Book, C.R. No. 64) surveyed the east-west road at this corner.

10-11-1870 J.V. Daniels, Surveyor, probably used this corner in Plat of School Section 36.

1875 State law required monuments to be set at township corners. Thomas Hunter, County Surveyor, placed stone monuments as required although there are no survey notes documenting this particular corner.

5-18-1891 Thomas Fraser, County Surveyor, (Book A, Page 457, Survey No. 441), "We found the township corner as set by Thomas Hunter, lettered and all right."

6-1896 William Fraser, County Surveyor, per Thomas Hunter, Deputy, (Book A, Page 603, Survey No. 548), "Found stone monument as town corner set by me under state law where the original corner stood. Said monument being 8 inches square and 30 inches long properly marked."

4-1-1898 William Fraser, County Surveyor, (Book A, Page 617, Survey No. 560) used corner (no description) for a survey in the N.E. 1/4 Section 1, Rochester Twp. He shows the 1/16th West (1322.0) but gives no description.

7-6-1913 D. Williams, County Surveyor, (Book B, Page 226) found limestone monument in the center of Zumbro Street.

12-15-1915 D. Williams, County Surveyor, found and used stone monument for Auditor's Plat-"A".

12-19-1918 D. Williams, County Surveyor, found and used stone monument for Sanderson's Second Addition.

6-9-1922 Charles Armstrong, County Surveyor, (Book B, Pages 384-385) found and used "Stone Monument".

11-15-1950 County Highway Department, (C.H.D. Book #186) shows "Iron pin" over stone monument. P.I. Sta. 0+00. RPs - Spike & Disc in PP NE 41.2', Spike & Disc in PP NW 64.7', Disc in fence post S 50.1', Spike & Disc in 18" Maple SE 66.5'.

11-10-1972 Roger Brand, County Surveyor, found iron rod at surface. Dug and found iron rod set over engraved stone monument down 1.7'. Set Cast Iron Monument at surface over stone monument.

6-24-1975 McGhie & Betts, Inc. found and used Cast Iron Monument for Weis Re-Subdivision.

7-13-1979 County Survey Crew found and traversed Cast Iron Monument in horizontal control survey (1979 Remonumentation Book, Page 103).

3-11-1980 County Survey Crew found Cast Iron Monument and took additional references and removed Cast Iron Monument and Stone Monument prior to sewer construction. RPs - Punch cross in SE corner of light base WNW 83.63', CSD in north side PP WSW 124.05', Spike & CSD in scar on north side 16" pine SW 101.65'.

9-8-1981 County Survey Crew set Cast Iron Monument over 5/8" rod at surface after sewer construction.

6-3-1985 County Survey Crew found Cast Iron Monument and took reference points before construction and removed monument. Set 1/2" rerod for temporary point. RPs - PK nail in saw joint in concrete median SW 82.42', PK nail in saw joint in concrete curb SSE 69.46'.

10-24-1985 County Survey Crew set 1" square pipe w/cap RLS #8952 at surface after construction from reference points established 6-3-1985.

10-1-2002 County Survey Crew found 1" square pipe with busted cap at surface in good condition.

2-5-2003 County Survey Crew removed remnants of old cap and set new cap RLS #15809 in pipe at surface and measured its position using GPS.