Certificate of Location of Government Corner

ID#: 733205 **Description:** S SEC COR 31 32 73 **Date Set:** 11/18/2003 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 5 1/2' south of centerline of WBL of CSAH 9, 17.4' north of north face of median curb and 60' ENE of centerline NBL of CSAH 22 on curve
Ref pipe "Ramp" NW 362.98'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, John Ball, Deputy Surveyor, West between sections 5 and 32. 80.00 set sec corner.
Burr Oak 14" N65°W 19 lks. Burr Oak 10" N63°E 55 lks. Burr Oak 15" S75°W 66 lks. Burr Oak 12" S14°E 124 lks.

3-1878 T. Hunter Bk.5 P.43 - used corner.

5-1891 T. Fraser P.457, No.441 S31, State of MN Corner gone, reset stake from bearing tree. The corner came in line with the fence running South. Set a stake and stone at the S. 1/4 corn. 31. on line between the section corners and at proprated Gov't Measure.

6-1896 T. Hunter P.603, No.548 S6 Hulburt, Coe, Brackenridge. Corner gone, replaced SE Bearing tree. 16W set temp stake. The corner came in line with an old fence running South.

6-1899 W. Fraser, P.658 No.586 S32, State of MN. Found stake, set 2"x7"x16" stone by stake 16 east set stake.

9-1965 John Kerr, County Surveyor, found 1/2" rod below the road surface. Set CIM over original rod with 1"x16" pipe.

4-29-1974 County Surveyor found 1/2" rod & county highway department nails. Stone gone. Reset CIM over 1/2" rod accepted corner location.

7-16-76 County Surveyor dug with the jackhammer and found W. Fraser stone, set 120d on south side of stone & iron. Set a 1/2" x 2' rod at the surface.

6-27-1977 County Surveyor replaced the 1/2" rod set 7-16-1976 with a CIM over stone w/chrome pieces. The corner is 4.7' South and 6.8' East of the C.I.M. (removed) set in 4-29-1974 at Kerr's corner.

7-1979 County Surveyor shot corner in control survey (1979 Remon. Bk. Pg. 103).

6-14-1995 county highway department referenced CIM before construction of intersection CR #9 and (East Circle Drive) CSAH #22.

2-17-1999 County Surveyor found CIM with head broken off but in good condition.

11-18-2003 County Surveyor found CIM down 0.5' with head broken off. Removed CIM and set 1" square pipe w/cap at surface from local ties.