Certificate of Location of Government Corner

ID#: 733304 **Description:** S 1/4 SEC COR 33 73 **Date Set:** **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 13W **Monument Description:**

Reference Ties:

The corner falls 16 1/2' south of centerline of CSAH 9 and 8 1/2' east of centerline of residential driveway north
This corner is located by GPS measurement

Corner History:

9-17 to 9-28, 1853 J. Ball, Deputy Surveyor, measured west 40.00 chains between sections 4 & 33. Set section post, made mound and trench. Planted Osage Orange seeds SE and Apple seeds NE.

10-6-1857 J. Fellows, (Book A, Page 41, Survey No. 63), shows quarter post. Shows 1/16 west with measure.

4-1-1878 T. Hunter, County Surveyor, (Book A, Page 333, Survey No. 327), "Quarter post missing and no remains of it could be found by the most careful search, but Mr. John Clark, an old settler who owns land on the north and east of 'B' avers that he built his fence running north from 'B' exactly on line with said quarter post when standing. We therefore reset it in according therewith and planted boulder stone in center of road. Which stone is 58 links north and 3 links west of corner post of fence running south on south side of road." 1/16 West set stake M&L at 20.18 chains (1331.88 feet). Note: In T. Hunter's field notes (Field Book #3, Pages 123-124, dated 8-28-1874) he states the above except he mentions setting a 2 ½"x10"x24" limestone as the corner.

8-26-1884 T. Hunter, County Surveyor, (Book A, Page 391, Survey No. 382), found stone as set in Survey No. 327.

11-18-1892 T. Fraser, County Surveyor, (Book A, Page 499, Survey No. 470), "As the ground was frozen hard at this corner we used the fence as recorded in Survey No. 327 Page 333 which said that the stone was set 3 links west and 58 links north of the fence running south."

1963 County Highway Department Corner assumed and used many years. CSAH 9 roll map shows monument with ties at P.I. Sta. 106+38.25

1968 County Highway Department may have set Cast Iron Monument after construction.

6-2-1969 J. Kerr, County Surveyor, reset corner with 1/2" rod. Proved corner by measure and angle to center of RR south as close as possible without running quarter line. Set ¾" x 36" pipe up 3" south 100' on transit line.

10-18-1972 R. Brand, County Surveyor, not satisfied with corner as set dug massive hole from CHD corner location east to fence running south after running quarter line from the north. Found limerock fill and very wet black soil below. Found nothing further.

11-24-1972 R. Brand, County Surveyor, dug from CHD corner location west, after running quarter line from south, and found limestone (3"x10"x?") in equally deep, wet hole. Stone falls 6.17' west of CHD corner location. Removed old CIM and points below. Set CIM over 1-¼" x 3' pipe over limestone and took new set of RPs. RPs - Spike in PP S 28.9', County Highway Disc in south end wood culvert headwall N 53.55', County Highway Disc in NE side TP NW 68.69', Bottle cap in W side PP #19068 SSE 29.51', Punch hole in E end 30" CMP SW 27.12'

CORRECTION OF A CORNER: The correct corner is 6.17' west of County Highway Department assumed rod.

10-19-1979 County Surveyor found and shot CIM in control survey.

5-23-1989 County Survey Crew found CIM down 1.3' in gravel shoulder of CSAH 9.

12-1-2003 County Survey Crew found CIM down 1' in good condition and measured its position using GPS.

4-24-2017 County Survey Crew found CIM down 1.3' in good condition and removed prior to road construction.