Certificate of Location of Government Corner

ID#: 733406 **Description:** 1/4 SEC COR 33 34 73 **Date Set:** 10/17/2005 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' east of centerline of N-S twp road, 1' south of fence east and 12 1/2' north of centerline of field entrance west
County Survey Disk in CP E 38.78'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes - William B. Yerby, Deputy Surveyor North between sections 33 and 34. 40.00 chs. Set quarter section post, made trench, mound, & planted osage orange seeds E&W of trench.

10-6-1857 John B. Fellows, Surveyor, (Book A, Page 41, No. 63) possibly used this corner to set the Center 33.

5-15&16-1876 Thomas Hunter, County Surveyor, (Book A, Page 292, No. 287, and Old Fieldbook 4, Pages 112-113) "1/4 post missing, but John Clark avers that he set the corner post of his fence running South and West exactly in mound where original corner post stood--We therefore took said corner post as the true corner." He used this corner to set the Center 34, a stake, at intersecting 1/4 lines; the 1/16 East, a stake, midway (19.80-1/2 chs.) and on line to the center 34; and the 1/16 East of the Center 34, a stake, midway (19.97 chs.) and on line between the Center 34 and the E. 1/4 Cor. 34.

11-1892 T. Fraser P.499, No.470 couldn't find corner. Set temp point M&L, no measure. 16N set stake M&L, no meas. 16W set temp stake for line N M&L no measure.

1959 J. Kerr, Bk79, Pg70 - Found remains of post hole. Set rod in center of hole.

10-1963 J. Kerr set CIM over 1/2"x2' rod. Line of fence running east S 3.0'.

10-1972 County Surveyor found CIM, found stone at 27-28-33-34, stone & iron at center 33, pipe in blacktop at S33-34. Used corner to run line west. Corner lies .85' west of direct line.

1979 County Surveyor shot CIM in control survey.

7-1-1980 County Surveyor dug on west side Kerr's CIM. Found square mark 2.26', North & 4.8'W. Dug also from 4' East of CIM east for 9' by 11/2' deep. Found square post mark 9.0 east & 2.0 north of CIM. Found another post mark 5.8' east and 2.0' north of the CIM. This post went deeper than the other 2. Set spike at road surface. Post approx 6' east - 6.15'WSW CIM & 9.75' NE to nail. Post approx 9' east - 9.25'WSW CIM & 9.05' north to nail.

7-2-1980 County Surveyor dug at the 1/16 East but did not find anything.
& 7-17-1991

7-28-1981 County Surveyor removed Kerr's C.I.M. and reset it over a 1/2"x24" rod over the post found 5.8' East and 2.0' North. With the corner set at this location the corner post at the Center 34 falls at the intersection of the 1/4 lines and the measure East to the Center 34 (2615.31) fits Hunter's closely.

8-1996 Dean Strange of peoples Coop found CIM at surface.

10-17-2005 County Surveyor found CIM without head down 0.5' with slight lean south. Removed CIM and found 1/2" rerod down 2' in good condition. Set 5 1/2' telspar pipe w/cast iron cap over 1/2" rerod down 0.4'.