Certificate of Location of Government Corner

ID#: 733505 **Description:** S SEC COR 34 35 73 **Date Set:** **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 13W **Monument Description:**

Reference Ties:

The corner falls in centerline of CSAH 9, in line with fence south and 6 1/2' east of centerline of driveway north
This corner is located by GPS measurement

Corner History:

9-30-1853 J. Ball, Deputy Surveyor, measured west 80.00 chains between sections 2 & 35 and set section post to sections 2-3-34-35. RPs - 14" Bur Oak N 64° E 170 links (112.20'), 12" Bur Oak N 32° W 150 links (99.00'), 16" Bur Oak S 83° E 259 links (170.94'), 6" Bur Oak S 85 1/2° W 24 links (15.84')

6-30-1857 J. Fellows, (Book A, Pg. 26, No. 42), used section corner.

6-5-1873 T. Hunter, County Surveyor, (Book A, Pg. 228, No. 231), found and used stone in center of road which tested within 1 link of SE bearing tree stump. Other bearing trees gone.

10-11-1882 T. Hunter, County Surveyor, (Field Bk. 5, Pg. 145), failed to find stone, but found stump of SE bearing tree.

12-31-1937 County Highway Department, (Bk. 88, Pg. 9 & 73), set bridge spike in center of road 2626.5' south of flat limestone at 1/4 Section Corner 34-35. PI Sta. 186+02.7 RPs - Tack in CP S 30.2', Spike in Oak N 84.9', Spike in top of FP SE 59.2', Hub SW 100.0'

8-21-1962 J. Kerr, County Surveyor, (J. Kerr Survey Book, Pg. 64 & Field Bk. 85, Pg. 74), shows 60d spike over stone.

5-15-1963 County Highway Department, (Bk. 277, Pg. 7), shows 60d spike. PI Sta. 185+69.14. RPs - Spike & Disc in top of FP NE 52.69', Spike & Disc in top of FP NW 59.21', Spike in TP NNW 56.24', Spike in PP S 47.51'

1966 County Highway Department set Cast Iron Monument over 1/2" rod from ties after road construction.

4-3-1973 County Surveyor found CIM down 0.2' set by County Highway Department.

12-1-2003 County Survey Crew found CIM down 0.8' in good condition.

12-2-2003 County Survey Crew removed CIM and found 1/2" rod down 2.3' in good condition.

12-8-2003 County Survey Crew set 1" square pipe w/cap at surface at CIM location and measured its position using GPS.

4-24-2017 County Survey Crew found 1" square pipe w/cap at surface in good condition and removed prior to road construction.