Certificate of Location of Government Corner

ID#: 740806 **Description:** 1/4 SEC COR 7 8 74 **Date Set:** 7/21/2003 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of 50th Ave NW and 22' South of centerline of Foxfield Pl NW
County highway disk in PP #36445 NNE 114.14'
County Survey Disk in PP #46315 SSE 143.20'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M. Karrick 40.00 set 1/4 section post in trench, pit, charred stake, and Osage Orange seeds NE & SW.

7-1857 J. Fellows Pg. 26 No. 41 - Used 1/4 Cor. meas. south 40.20 chs. meas. east 40.05 chs. 1/16 n. 20.00 chs.

5-1867 HE Horton, Pg. 84 No. 129 - Shows 1/4 cor. used to break down west half section 8 Meas. south 40.06 chs. 1/16 east 19.92 1/2 chs. to cen. sec. 1/16 north 20.03 1/2 chs. M&L.

5-1876 T. Hunter P. 295 No. 290 corner gone. Set stone 2x4/12x23 M&L 40.19 (2652.54'). 16 north set stone 2x5x15 M&L 20.091/2 (1326.27'). 16 south set stone 4x4/10x22 M&L 20.091/2 (1326.27'). 16 west set stone 11/2x9x18 M&L 19.92 (1314.72').
16 center NE 1/4 sec. 7 set stone intersecting lines. 16 center SE 1/4 sec. 7 set stone 11/2x6/15 inter. lines.

1938 Co. Hwy. Dept. B103, P.51 Found flat limestone. Disc in cor. F P E 20.4. Disc TP SW 68.5. Meas. N 1326 to 1/16 found then 1325.0-16 north came in line fence west and road south.

1941 B25 P37 - Cascade twp. rd. survey found stones & iron rod. 2651.3 south to SW cor. 8.

6-19-64 J. Kerr - Found iron, stones & glass. Set CIM over 11/2"x4" pipe. Corner lies in line of fence running east. Corner lies 2' west center road. Disc power pole SSE 144.7 Disc power pole NNE 114.2 3/4"x28" pipe up 9" in fence line east 100.0.

11-8-77 County Surveyor found CIM leaning. Dug down to pipe and reset CIM over it. Pipe was .2N. & .5W. Set sign and post in fence line west.

11-20-1989 County Surveyor found spike, found CIM down 14".

11-22-1989 County Surveyor set 10" CIM over CIM.

7-26-2001 Mn/DOT Survey Crew found monument in good condition.

3-14-2002 County Surveyor found CIM in good condition down 0.4'.

7-25-2002 County Surveyor set 2 points to tie out corner for 2002 construction.

7-10-2003 County Surveyor set pk nail at surface from 2002 construction tie-out.

7-21-2003 County Surveyor set 1" square pipe w/cap at surface over p.k. nail.

8-14-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.