# Certificate of Location of Government Corner

**ID#:** 741009 **Description:** SEC CEN 10 74 **Date Set:** 11/2/2006 **County:** Olmsted

**Section:** 10 **Township:** 107N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in centerline of CR 112 and 6' south of fence east
This corner is located by GPS measurement

**Corner History:**

6-16-1874 T. Hunter P.256 No.256 set marked stake at inter. lines. 16 east set stake M&L 20.041/2 (1323.0). Meas. north 39.63 (2615.58 - south 39.44 (2603.04'). Meas. N-S 1/16 line NE1/4 1039.79 2626.14.

11-1916 J. Kerr P.252B set center 10 at final inter stone set 1/16 stone E at 1321.12 meas. west 2642.25 - north 2609.5 - south 2609.5.

1966 J. Kerr B93 P13 west 1/4 & E1/4 10 found previously. Also, N&S1/4 corners. meas. north, now 2615.3 (1916 2609.5). meas. east, now 2632.14 (1916 2642.24). Set pipe at 16 east in bottom slope 1316.07 - Corner at first set 5' off due to misfiguring - corrected later. Rod set at 1800' from N1/4 10 on line.

1968 county highway department B337 found CIM Sta. 78+57.35 P.O.T. - meas. south 2598.73 meas. north 2619.91 - Sp D. stub PP W29.5, Sp D PP SW 138.75 - grading ties transit tie west from CIM 2x2 hub 79.43 then 2x2 hub further. (Summary latest corner - county total mile 5218.64. J. Kerr total 19162X2609.5 (5219.91.) Qualey survey, B93 P13 calls for meas. north 2615.3. Reset corner by Kerr notes. County meas. north 2619.91.

4-22-1977 McGhie and Betts set 5/8" pipe w/cap #11622 at center of section in survey in SW 1/4 sec 10.

7-21-1978 McGhie & Betts found and used 5/8" pipe.

10-29-1982 McGhie & Betts found and used 5/8" pipe.

5-14-1984 V. Fangman found and used 5/8" pipe.

9-29-1989 County Surveyor found 5/8" pipe/cap down in centerline of blacktop. Reset corner by J. Kerr notes.

1-10-2003 County Surveyor found 5/8" pipe w/cap missing down 0.4' in good condition.

10-24-2003 Yaggy Colby found and used 5/8" pipe.

1-8-2004 Yaggy Colby found and used 5/8" pipe.

2-2-2006 County Surveyor found 5/8" pipe w/cap in good condition down 0.4'. Both power poles have been replaced.

11-2-2006 County Surveyor set 1" square pipe w/cap at surface from 2006 overlay tie-out.

8-15-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.