Certificate of Location of Government Corner

ID#: 741905 **Description:** W SEC COR 19 30 74 **Date Set:** 8/6/2007 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' east of centerline of CR 104, in line with fence west and 1 1/2' S of fence east
3/8" Iron in fence line W 100.00'
Spike in NW side large Pine NW 130.3'
This corner is located by GPS measurement

Corner History:

8-1857 Hunter P. 36 No. 58 Used Corner, set 1/16 east 17.78 then 20.00 to N1/4 30.

4-1863 P.C. Compton, Pg. 72 No. 103, Shows sect. cor. (See survey for breakdown of Sec. 25) somewhere in the interum a stone was set and later found in center road in line fences E&W.

10-11-1877 Hunter P. 321, No. 315 Found old stake center road in line fences east and west. Meas. east 37.72 to old stake remains.

6-1936 county highway department Bk.81 Pg.24; found limestone monument 1' north of E-W fence line. RPs- 18" PINE nnw 99.0', corner post west 33.2'.

10-7-1963 J.Kerr set CIM over pipe. RPS-nailes to 24" larch tree 130.3'.

7-28-1966 J.Kerr set new CIM over old pipe Nail in hub on NE side 24" pine NW 130.3.

1968 Co. H.D. B. 335 found CIM broken again corner is PI 0deg. 9"20" rt. goind north Sta. 237+39.25. Meas. south 2637.5 north 2634.54.

6-12-1970 County Surveyor top on CIM broken and gone. Removed and found 1/2" rod below. Checks all ties, didn't reset CIM. Set 1/2" x 2' rod.

10-9-1986 County Surveyor fd 3/8" rod and spike in NE side large pine 130.3 NW. Spike grown over and hub now lying on the ground. Found no other good reference points remaining. Found 5/8"x18" 11" deep and set corner here.

3-19-2002 County Surveyor found concrete nail at surface. Took ties and removed and found nothing.

5-2-2002 County Surveyor set 1"x2' square pipe w/cap at surface from angle turned previously. Corner falls 0.5' West of centerline of CR 104.

6-27-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-18-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

8-6-2007 County Surveyor set 1" square pipe w/cap at surface from 2007 overlay tieout. Did not check any ties.