Certificate of Location of Government Corner

ID#: 742104 **Description:** 1/4 SEC COR 21 28 74 **Date Set:** 4/20/2017 **County:** Olmsted

Section: 21 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with center line of private road north
The monument is down 0.2'
Post w/sign 2' east
This corner is located by GPS measurement

Corner History:

6-23-1854 M. Karrick - Gov't Notes - East on random line 40.00 chains set temporary 1/4 section post. West on true line between sections 21-28, 40.00 chains set 1/4 section post in mound with trench, pits, charred stake, and osage orange seeds NE & SW.

6-26-1863 P.C. Compton (Book A, Pg. 74, No. 108) used 1/4 post to set center 21.

11-17-1863 P.C.Compton (Book A, Pg. 78, No. 117) used 1/4 post to set center 28.

10-8-1936 County Highway Department (Bk. 89, Pg. 75) Set square iron spike for corner. RPs - 303' E of RR, 486' N of RR, 612' diagonal measure.

8-22-1940 County Highway Department (Bk. 119, Pg. 56) Set red head midway and on line as S 1/4 corner section 21.

1956 K. McGhie, in IBM land survey, found 1"x2" hub and replaced with 5/8" rod. RPs - Spike in TP SW 36.5', Spike in FP NW 38.35', Steel FP W 30.25'

6-9-1960 J. Kerr found rod to be midway and 8.45' north of straight line between section corners and 491.1' north of center line of County Road 4 as in place 1960.

8-1972 County Highway Department reset 3/4" iron rod as 1/4 corner after construction. RPs - N&D in curb NW 6.76', N&D in curb SW 7.11'

8-5-1975 Center SW 1/4 Section 21 County Surveyor dug and found 1-3/4" x 40" pipe over pointed limestone & wood stake 5' deep. Set scrap iron and stone around stone and reset pipe over all. RPs W edge 6" square iron post up 3-1/2' NE 55.6'

2-22-1984 County Surveyor found 5/8" rerod in blacktop. Ties in curb gone so could not verify ties. Shot rod.

10-21-1986 County Surveyor found new lift of blacktop over iron. Dug and found 5/8" rod lying flat over another 5/8" rod down 2-1/2" and firm. Can't be sure which iron was shot in 1984.

2-3-1999 County Survey Crew found pk nail at surface. Corner falls 2-1/2' west extension center line of CR 151 from north.

8-27-2002 County Survey Crew found pk nail at surface in good condition.

8-29-2002 County Survey Crew removed pk nail and found 5/8" iron rod. Set 1" square pipe with cap over rod and down 0.2' and located position using GPS. RPs - CSD in PP NW 68.55'

10-15-2007 County Survey Crew found 1" square pipe w/cap down 0.1' in good condition.

4-20-2017 County Survey Crew set 3' telspar pipe with Cast Iron Cap down 0.2' at previous GPS position after road construction.