Certificate of Location of Government Corner

ID#: 743005 **Description:** W SEC COR 30 31 74 **Date Set:** 8/6/2007 **County:** Olmsted

Section: 30 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 44 and in centerline of township road west (14th St NW)
The monument is at the surface
County Highway Disc in N side PP #10406 E 44.84'
This corner is located by GPS measurement

Corner History:

10-4-1853 John Ball, Deputy Surveyor, measured north 80.00 chains between Sections 31 and 36. Set post and drove charred stake. Corner to Sections 25, 30, 31 and 36. Built mound and dug trench per instructions. Planted Osage Orange seed SE and Apple seed NE.

5-30-1854 Michael G. Karrick, Deputy Surveyor, measured east 80.00 chains on random line, between Sections 25 and 36, for subdivision of Kalmar Township. Intersected east boundary at post.

6-24-1854 Michael G. Karrick, Deputy Surveyor, measured west 77.25 chains on random line, between Sections 30 and 31, for subdivision of Cascade Township. Intersected west boundary at post.

7-17-1857 E.P. Bircher, by John B. Fellows, Deputy, (Old Road Book, Pages 69-70, Road No. 73 and New Road Book, Page 174, Road No. 73), used post for road survey.

8-19-1857 E.P. Bircher, by Thomas Hunter, Deputy, (Old Road Book, Page 30, Road No. 34 and New Road Book, Page 120, Road No. 34), used post for road survey.

8-24-1857 E.P. Bircher, by Thomas Hunter, Deputy, (Old Road Book, Page 67, Road No. 71 and New Road Book, Page 172, Road No. 71), used post for road survey.

6-2-1870 Robert Perry, County Surveyor, (Book A, Page 120, Survey No. 155), "found post put in by me in previous survey." RP - SE corner of school house N41°50'W 2.32 chains (153.12'). 1/16th West "found post put in by me in previous survey."

9-4-1874 Thomas Hunter, County Surveyor, (Book A, Page 260, Survey No. 259 and Old Field Book No. 3, Page 126), "found remains of old stake in center of road. Set quarry stone in its place." He shows 1/16th West stone midway and on line at 20.00 chains (1320.00'), but doesn't mention in the survey explanation.

12-7-1921 John Kerr, (Book B, Pages 374-375 and Kerr Field Book No. -9, Pages 27-30), found old stake in the clay after much digging. Set 4"x5"x19" stone packed in broken stone and drove iron pipe in place of stake. RPs - SE corner concrete foundation of school house NW 134.8', Spike in telephone pole NE 39.8'.

6-10-1936 County Highway Department (CHD Book No. 81, Page 24), found limestone monument with a pipe under it. RPs - SE corner of front annex of school house NW 134.8', East side telephone pole SW 84.5', Spike in telephone pole NE 35.5'

1941 John Kerr, County Surveyor, (Kerr Field Book No. 25, Page 36), 4"x6"x16" limestone running to edge on top with notch in top.

7-28-1959 John Kerr, County Surveyor, (Kerr Field Book No. 79, Page 39), found 1" pipe and set 2" pipe riser. RPs - SE corner school entry NW 134.9', Spike in telephone pole NE 37.65', Spike in east side power pole SE 54.6', Spike in north side power pole SW 92.6'.

9-27-1961 John Kerr, County Surveyor, (Kerr Field Book No. 84, Page 23), found 2" pipe and set Cast Iron Monument over iron pipe.

5-1968 County Highway Department, (CHD Book No. 335, Page 3), found Cast Iron Monument. P.I. Sta. 184+63.80. RPs - Spike in power pole SE 54.60', Spike in power pole SW 92.60'.

6-22-1972 Roger Brand, County Surveyor, removed Cast Iron Monument prior to road construction and set 1/2"x26" rod in its place. Took transit ties to the corner.

6-30-1983 County Survey Crew found 5/8" rod down 1.2' which was 0.28' South and 0.20' West of 1972 transit tie position. Removed 5/8" rod and set Cast Iron Monument over 5/8" rod at transit tie location. The corner falls in centerline of CR 104 and in centerline of township road west. RPs - County Highway Disc in south side power pole NW 90.77', Plasitc County Highway Disc in north side power pole E 44.89', Spud in north side power pole SW 92.75'.

2-8-2002 County Survey Crew found Cast Iron Monument down 0.3' in good condition and measured its position using GPS.

5-18-2007 County Survey Crew found Cast Iron Monument down 0.3' in good condition. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. Removed Cast Iron Monument.

8-6-2007 County Survey Crew set 1" square pipe w/cap at surface from references for 2007 bituminous overlay project. The corner falls in centerline of CR 104 and in centerline of township road west. RP - County Highway Disc in north side power pole #10406 E 44.84'.