Certificate of Location of Government Corner

ID#: 743306 **Description:** 1/4 SEC COR 32 33 74 **Date Set:** **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 14W **Monument Description:** Corner falls under Harriet Bishop Elementary School

Reference Ties:

Witness corner falls 1.4' west of west side of N-S sidewalk
NW corner Harriet Bishop School NE 47.96'
SW corner Harriet Bishop School ESE 67.43
Actual 1/4 corner falls under school
This corner is located by GPS reference stations "Bishop & Harriet"

Corner History:

1854 Gov't Notes, Karrick, Deputy Surveyor, North between sections 32 and 33. 40.00 chs. Set quarter section post in mound with trench and pits and charred stake. Planted Osage orange seeds N.E. and S.W.

10-1894 William Fraser (P. 554 No. 511), Co. Surveyor, found corner post marked by Hunter as 1/4 corner. Set stone and stake midway and on line at 1/16 west.

3-1954 John Kerr, (P. 64 B. 57), County Surveyor, ran and measured section line between Section 32 and Section 33. Set 1/2" rod midway and on line.

6-18-1975 County Surveyor, corner now comes under Harriet Bishop School. Reset a witness corner with 3/4"x12" rod 101.62' west of actual corner location and on the East-West 1/4 line of Section 32. For east-west control we used a distance of 574.88' from a 1/2" pipe found on the East line of Country Club Manor 1st Subdivision. By resetting the corner this way we maintain the corner location from when Country Club Manor was platted.

11-1987 County Surveyor, witness iron gone, but untied loc and shot. Also reshot CC Manor 1/2" pipe. Recomp corner based on these two points and E 1/4 33 using dwg 3-57. See dwg No8 for coord.