Certificate of Location of Government Corner

ID#: 750406 **Description:** 1/4 SEC COR 4 5 75 **Date Set:** 10/19/2006 **County:** Olmsted

Section: 04 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of E-NW fence
County Survey Disk in N side 36" twin Oak E 7.05'
County Survey Disk in W side 24" Oak S 7.91'
Post w/sign 2' east
This corner is located by GPS reference stations "Rusty A & B"

Corner History:

1854 Gov't Notes: Karrick 40.00 set temp 1/4 section post S 10' W on true line between section 4&5. White Oak 8 S 50 E 75. White Oak 18 S 44 W 51.

1-1870 R. Perry (P.95 No.139) SE 1/4 S.5 used corner, set stake West 10.00 then 8.75.

11-1916 J. Kerr (P.260B) set stone and broken glass around it on line at prop distances from NW cor section 4. 1/16 South stake 1310.52 M&L. 1/16 North set iron stake in broken glass 1310.52 then 1305.93 to iron stake and bolt as NW cor 4 as 1/4 cor 4-5 set stone in glass. 60d in 8" Pine Oak S 50° 30' W 11.61'. 60d in 10" Pine Oak S 23° 45' E 7.5'.

1947 J. Kerr (B.32 P.62) found stone in dry wash lying flat. Reset from SE witness tree with 3/8" x 26" rod. 60d in 14" Pine Oak S 23° 45' E 8' (both in 6-19-1970). 60d in 18" Elm East 8'. Meas North 2613.57 1916 2616.45. Meas South 2618.4 1916 2621.04 with points between.

6-19-1970 County Surveyor found J. Kerr corner and also 1/16 iron North see S 32-33. N. Haven line from N 4-5 (also found over 1/16 iron missed 3/8" rod on East side rod about .2' or very close both Oak and Elm trees in good shape. Rod in wash but new road helped save corner, will set CIM.

7-31-1985 RP's to re-rod at 1/4 cor 4-5 from Vince Fangman. 60d in 18" Pin Oak SE 8.09 (7-7-95 could not find). 8d in 12" Pin Oak WSW 30.70 (7-7-95 gone). 8d in S side twin Elm ESE 8.43 (7-7-95 could not find nail)

7-7-1995 Roger Brand and Associates found 3/8" rod in shallow small ditch running south. Set 5/8" pipe over 3/8" rod.

8-19-2003 County Surveyor at 1/16th north found 1" pipe down 0.1' leaning South and found 5/8" rerod down 0.3' leaning South 1' South of pipe.

9-4-2003 County Surveyor found 1/2" pipe w/cap RLS #8952 down 0.5' in good condition. Set 2 pts as GPS reference to verify position.

10-19-2006 County Surveyor found 1/2" pipe w/cap down 0.3' in good condition, took local ties. Set 3' telspar w/CIC up 0.3' over pipe. CSD w/60d nail in north side of 36" twin oak east 7.05'. CSD w/60d nail in west side of 24" oak south 7.91'.