Certificate of Location of Government Corner

ID#: 750704 **Description:** 1/4 SEC COR 7 18 75 **Date Set:** 3/22/77 **County:** Olmstted

Section: 07 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in S side CP WNW 2.13'
County Survey Disk in SW side 18" Black Oak SE 31.39'
County highway disk in E side PP #27063 S 49.05'
Post w/sign 2' east
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes; Michael Karrick, Deputy Surveyor; East on true line between sections 7 & 18. 39.00 chs set quarter section post. RPs- 6" aspen N53°E 155 links, 6" aspen S54°W 48 links. 79.00 chs -section corner.

4-1897 William Fraser, County Sureveyor, (Pg.607 No.552) could not find any stake at this corner, but a Mr. John Hoffman and others said the stake stood close to the North side of the corner post of the fence.

11-1938 John Kerr, County Surveyor, (Bk.14 Pg.13) Found a stone on the north side of the old fence corner post. Took the following references: 24" red oak east 12.4' (center), and 18" white oak NNE 33'.

11-1946 John Kerr (Bk.32 Pg.43) states that he found a fence post 36' north of the true corner, but didn't dig up the stone. He records a 1 1/4" pipe as the center 7.

9-1964 John Kerr (Bk.89 Pg.58) set CIM as the corner on the line between the section corners and at prorated Gov't measure.

3-11-1977 County Surveyor intersected the line from the north 1/4 corner 7 over Kerr's pipe at the center 7(found) with the south line of section 7. This point came approximately 14' east of Kerr's CIM and near the corner post, but found nothing. Also searched for the bearing trees taken by Kerr in 1938, but they were gone.

3-22-1977 County Surveyor set a CIC on a square pipe as the corner 13.76' east of Kerr's CIM (removed) at the intersection of the line from the n 1/4 corner 7 over the center 7 and from the SW corner section 7 over Kerr's CIM location at the south 1/4 corner 7 (which Kerr had set on line between the section corners).

Note: The correct corner is 13.76' east of Kerr's CIM (removed).

12-9-2004 County Surveyor found cast iron cap on telspar pipe with loose cap. Removed old bolt and replaced with new.