Certificate of Location of Government Corner

ID#: 750806 **Description:** 1/4 SEC COR 7 8 75 **Date Set:** 1/31/2012 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Monument on Telspar Pipe

Reference Ties:

The monument is up 0.2'
Center of Oak NNE 8.2'
Post w/sign 1 1/2' east
County Survey Disk in east side cedar fence CP SSW 19.9'
This corner is located by GPS reference stations "Buckwalter A & B"

Corner History:

5-1854 Gov't Notes: Michael Karrick, Deputy Surveyor; North between sections 7 & 8. 40.00 chs set quarter section post. RPs- 12" black oak S60°W 93 links, and 11" walnut S40°E 38 links.

12-3&6-1869 Robert Perry possibly used this corner to set the center 8, a post (see survey No.169 Pg.141-142 Bk. A January 17and 18 1871).

2-11&13-1871 Robert Perry, County Surveyor, (Bk.A No.171 Pg.145-146) used corner (no description) to check point established from bearing trees at the 1/16 west, an oak post marked 1/16S. Found it midway (20.27chs). He also set the 1/64 west of the 1/16 west, and a property corner 4.00 chains west of that. At the center 7, he found an old post standing."

1933 John Kerr, County Surveyor, (Kerr paperback fieldbook, Pg.26-28) shows"stone" at corner. Measured 2695.5 (measures actually add to 2699.5) south to "squared broken stake at SW corner.

1941 J. Kerr (card) measured 2695.0 from the SE corner 7 to stone at east 1/4 corner 7. Stone 9"x9"x30". (up 1.0')

1946 J. Kerr (Kerr Bk.32 Pg.41-44) measured from wood stake at sw corner 8 2698.56 north to 7"x10" topped limestone sticking up 15" at 1/4 corner 7-8.

10-5-1964 J. Kerr (Kerr Bk. 89, Pg.58 and card--cert filed) set a CIM over a 5/8"x14" rod with large 9"x9"x30" stone on the south side and a 1 1/4" pipe on the north side.

8-13-1974 County Surveyor found CIM set by Kerr.

5-7-1981 County Surveyor found CIM with stone on the south side and pipe in the north side.

1-31-2001 County Surveyor found CIM up 0.2' with slight lean west. Corner falls inside edge of woods.

1-31-2012 County survey crew found cast iron monument leaning westerly. Removed and found 5/8" iron rod down 2' in good condition directly below the base of the CIM. Set 4' Telspar pipe with cast iron cap over the rod.