Certificate of Location of Government Corner

ID#: 750905 **Description:** SEC COR 8 9 16 17 75 **Date Set:** **County:** Olmsted

Section: 09 **Township:** 107N **Range:** 15W **Monument Description:**

Reference Ties:

Spike & County Survey Disk in 10" Elm E 12.72'

Corner History:

5-1864 Gov't Notes: Michael Karrick, Deputy Surveyor, North between sections 16-17; 80.00 chs. Set post for section corner. RPs-12" elm S 55 W 18 links, 8" sugar N 48 W 34 links, 6" elm N 47 E 24 links, 10" walnut S 30 E 37 links.

3-1892 Thomas Fraser (Pg.474 No.453), County Surveyor states that corner gone in wash out. Set corner from SE bearing tree stumps of SW and NW bearing trees. Set witness stone and stake 15 links west.

6-1900 Robert Fraser (Pg.684 No.608) County Surveyor found witness stake with stones piled around it. Set new stake and stone.

11-1960 John Kerr (Kerr Book 80 Pg.57) County Surveyor found a stone standing on end on east side of ditch. Accepted this stone as corner and set a pipe on the side of it and set 1/4 corner north midway and line. Both these corners were found to be incorrect.

6-23-1970 County Surveyor found a stone that could be the recorded witness stoneset by R. Fraser on the west bank of the ditch. Set the stone up(was leaning)and piled other stones around it.

12-4-1975 County Surveyor enlarged hole by digging around witness stone, but found no other stones or stakes. Accepted the stone found in 1970 and removed it and set a 1"X2'pipe in its place as witness corner and then set a 1"x4' pipe in the ditch at 15 links(9.90')on a corrected magnetic bearing of east as the section corner. Left pipe stick up 2'.

Note: This is a correction of a corner. 3'north & 7.45' west of Kerr's stone.

2-6-2001 Witness Corner - County Surveyor found 1" pipe up 0.2' in good condition. Ties NW and WSW are gone. Spike in dead 10" Elm east 22.46'.

1-3-2006 Witness Corner: County Surveyor found 1" pipe laying flat because of ditch bank washing out.