Certificate of Location of Government Corner

ID#: 752004 **Description:** 1/4 SEC COR 20 29 75 **Date Set:** 10/23/2006 **County:** Olmsted

Section: 20 **Township:** 107N **Range:** 15W **Monument Description:** 1" copper plug w/punch mark RLS #15809

Reference Ties:

The corner falls 3 1/2' west of centerline of CSAH 5 and in line with south property line of Byron High School
5/8" rod with cap East on section line 63.79'
5/8" rod with cap West on section line 78.31'
5/8" rod with cap West on section line 178.31'
County Survey Disk in PP WNW 66.02'
This corner is located by GPS reference stations "Gemelke and Kuhlman"

Corner History:

6-1854 Gov't Notes: Michael Karrick, Deputy Surveyor; West on true line between sections 20 & 29 40.00 chs set quarter section post. RPs; 10" burr oak N54°E 193lks, 15" black oak S30°W 168 lks 80.00 chs section corner. Robert Perry apparently used the corner to set the Center 20. See Thomas Hunter's survey No. 253, Pg. 253, Book A, where he "Found stone near corner of fence, set by R. Perry, Surveyor as center section.

5-1871 Robert Perry, County Surveyor, (Book A, Pg. 162-167, No. 185) found a stone monument. Used this corner to set the Center 29, a temporary point at intersecting 1/4 lines, and to set the 1/64 South of the Center of section.

9-1933 John Kerr, County Surveyor, (Kerr Bk. 9, Pg.3) shows a stone on drawing midway (2630.35) between stones at the NE corner 29 and the NW corner 29.

9-1936 The county highway department (county highway department Bk. 84, Pg. 72) set a square spike for this corner midway (2629.2) and on line between stones at the NE corner 29 (8"x8"x4" limestone) and the NW corner 29 (8"x8"x6" limestone).

1937 The county highway department (county highway department Bk. 378) set a 60d spike. Set this point on the inplace fence line by backing tangent in over the center section from the N 1/4 corner of section 20.

8-21-1974 The County Surveyor ran line from the N 1/4 corner 20 (CIM over stone found in 1970) over the center 20 (CIM over stone found in 1974). Line fell 1.52 W of 5/8" rod found at the road surface. Dug for the corner but found nothing further. Set a 5/8" rod as the corner on line from the North (and opposite the 5/8" rod found removed) and in line with fence West. Also dug for the center 29, but didn't find corner.

5-13-1980 County Surveyor took references to the iron in place before road grading.

11-5-1980 county highway department (county highway department Bk. 406, Pg. 3) set a rerod after road grading.

3-12-1981 County Surveyor set a 5/8" rod with cap as the corner from reference points taken 5-13-1980. Removed county highway department iron which slightly disagreed with the County Surveyor's references.

12-4-1982 County Surveyor set a 1" square by 6" long pipe with cap from references taken 5-13-1980 in new concrete on CR 5. In 1974 the County Surveyor set this corner E-W on the 1/4 line of section 20 from the monuments in place at the Center and N 1/4 corner. He accepted the fence line running West to set the corner N-S as the best evidence of the corners previous location.

5-21-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

10-23-2006 County Surveyor set 1" copper plug w/punch mark at surface.