Certificate of Location of Government Corner

ID#: 752006 **Description:** 1/4 SEC COR 19 20 75 **Date Set:** 10/22/2007 **County:** Olmsted

Section: 20 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of E-W twp road, 52' west of centerline of field entrance north and 79' west of centerline of driveway south
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 40.0 set 1/4 section post. RPs- 10" burr oak 547 W 145 links, 17" burr oak 524E 175 links.

5-1874 T. Hunter Bk.3 Pg.101-102; At D found old stub of stake & also stone set by Perry from bearing trees, one of which the SE is still standing, also found blazed tree about on line of stone north, distance of stone from SE bearing tree is 192'.

6-1895 W. Fraser Pg.578 No.528; Corner gone, in road cut, on aver of Mr. DT Tompkins. Set temperary stake in line fence south and 2 rods north of willow row south side of road, both set by original stake.

4-1911 Charles Larson Pg.152B; Found corner.

10-31-1964 J. Kerr set CIM over 5/8"x14" rod. RPs- Just north of oak tree base, Center 18" oak tree S 58.0', disc telephone pole 51.2', punched cross in west end field culv. NE 49.78', fence running south E 4.0'.

3-1979 Ron Olson(Zenk Eng.) called to report that 1/4 line from section 20 came 3' south of this 1/4 corner, used inpl. Monument for his survey.

12-15-2004 County Surveyor found CIM down 0.9' in good condition.

10-22-2007 County Surveyor found CIM down 1.1' in good condition. Removed CIM and found 5/8" rerod down 2.8' in good condition. Removed 5/8" rerod and set 5 1/2' telspar pipe w/cast iron cap down 0.4' at CIM position.