Certificate of Location of Government Corner

ID#: 752204 **Description:** 1/4 SEC COR 22 27 75 **Date Set:** 9/5/2001 **County:** Olmsted

Section: 22 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1 1/2' E of centerline of CSAH 3, 1 1/2' N of centerline of twp road west and 2 1/2' south of fence east
County Survey Disk in PP #12586 NW 62.37'
County Survey Disk in CP E 55.10'
+ punched in CMP NW 36.75'
+ punched in CMP SW 40.92'
Ref pipe E 50.41'
This corner is located by GPS measurement

Corner History:

1854 Gov'tNotes: Karrick; 40.0 set temperary 1/4 section post west on true line between sections 22 & 27 V 9° 7'. 40.0 set 1/4 section post in mound with trench, pits, charred stake, and planted osage orange seeds NE & SW.

4-1870 R. Perry Pg.106 No.145; Found original stake, mound, and pits, with new stake put in 1868. Set stone 3x9x37 even with surface. Renewed mounds and pits with old stake in center mound over stone. RPs-5" jack oak S 28° 85 links, 4" burr oak N 41 1/2 W 73

6-1901 Robert Fraser Pg.699 No.618; Found stone, tested bearing trees, lines fence east a little west of center of road. 1/16 east set stone 6x9x18 M & L 19.83 1/2 (1309.1')

8-1927 county highway department B51 Pg.67 found stone. Measured south 2629.9 to stone at center 27.

1964 county highway department Bk.270 Pg.1, found 4"x18"x18" limestone. Set 2x2 hub riser. RPs- spike in fence post east 61.55, corner fence post SW 62.47', spike & disc in power pole NW 47.35', spike & disc in corner post E 27.13", spike & disc in corner post SE 40.37'. Measured S to 1/4 27-34 5275.6 (see center 27).

10-31-1964 J. Kerr set CIM over 5/8" rod over corner. RPs- disc in power pole NW 62.4', +punched cross in galv. Culvert NW 36.7', + punched cross in galv culv. SW 40.95'.

6-6-1986 County Surveyor found monument 19' deep in blacktop road.

6-16-1986 County Surveyor set 10" CIM corner in centerline and 2 1/2' south of fence east. RPs- punch mark (+) in lug at north end culvert NW 36.75', punch mark(+) in lug at south end of culvert SW 40.92'.

6-4-2001 County Surveyor found CIM at surface in good condition. Found 5/8" pipe w/cap at R/W East of corner and used as ref pipe. Tied out corner and removed CIM.

8-30-2001 County Surveyor set pk nail at surface from 2001 overlay tie out.

9-5-2001 County Surveyor set 1" square pipe w/cap at surface from 2001 overlay tie-out.

6-27-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.