Certificate of Location of Government Corner

ID#: 752804 **Description:** 1/4 SEC COR 28 33 75 **Date Set:** 10/14/2005 **County:** Olmsted

Section: 28 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap #42638

Reference Ties:

The monument is at the surface
The corner falls in centerline of CR 134 and in centerline of 10th Ave NE
County Survey Disk in PP NE 66.31'
County Survey Disk in PP SE 82.90'
County Survey Disk in PP SW 75.08'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 40.00 set temperary 1/4 section post west on true line between sections 28 & 3 V 9° 10'. 40.0 set 1/4 section post in mound with trench, pits, charred stake, and planted osage orange seeds NE & SW.

7-1893 W Fraser Pg.525 No.490 corner gone, dug rod square, set stone 6x6x24 M & L 39.93 2/3 to section coarner found east, set west.

10-1919 Bound field book at Mcghie & Betts. See copy at back of blue notebook. Indicates something used as 1/4 corner and measured south to center 33, 2622.5.

6-29-1964 John Kerr found iron. Set CIM over 3/4"x12" iron.

NOTE: T. Hunter's RR notes, 2049 south to centerline RR tracks.

6-5-2001 County Surveyor found CIM down 1.6' in good condition. Set 1" square pipe w/cap as ref pipe for 2001 overlays. Tied out corner.

8-30-2001 County Surveyor set pk nail at surface from 2001 overlay tie out

8-31-2001 County Surveyor set 1" square pipe w/cap at surface.

5-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

7-30-2002 County Surveyor found 1" square pipe w/cap at surface in good condition. Corner to be destroyed with construction of 10th Ave NW North & South of intersection. Set new ref pipe and tied out corner.

2-4-2005 WHKS Survey Crew found pipe with aluminum cap missing.

2-11-2005 County Surveyor found pipe w/cap missing and top of pipe damaged. Did locate ref. Monument. Will replace monument during warmer weather because of blacktop replacement.

6-14-2005 County Surveyor found 1" square pipe without cap down 0.4' bent. Removed pipe.

10-14-2005 County Surveyor set 1" square pipe w/cap at surface from 2002 tie out.

8-24-2011 County survey crew found 1" square pipe with damaged cap. Replaced with a new survey cap.