Certificate of Location of Government Corner

ID#: 752904 **Description:** 1/4 SEC COR 29 32 75 **Date Set:** 6/9/00 **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' east of centerline of CSAH 5 and 1' south of centerline of CR 134
Ref pipe SE 45.88'
County Survey Disk in PP #35 ESE 78.19'
County Survey Disk in PP #40 SW 42.77'
Top nut of fire #40 SE 53.32'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: Michael Karrickk, Deputy Surveyor; West on true line between sections 29 & 32. 40.0 chs. set 1/4 section post in mound with trench, pits, charred stake and planted osage orange seeds NE & SW. 80.0 chs.-section corner.

4-1861 Samuel McDowell, Surveyor, (Bk.A Pg.66 No.93) may have used this corner to set the center 32.

11-25-1867 George Healy, Surveyor possibly used this corner to set the 1/16 south and the center 32 (a stone shown on plat) for the survey of Byron.

11-1867 Robert Perry, Surveyor used this corner to survey the Byron Cemetary.

10-1868 Robert Perry, Surveyor shows a stone monument at 1/4 corner 29-32 and a measure of 19.84 chs. South to a stone monument at the 1/16 south in the plat Diebell and Westcott's Additrion to Byron.

5-1870 Robert Perry, County Surveyor, (Bk.A Pg.114 No.150)may have used the corner (N-S 1/4 line being west line of plat) to survey Newells Additon to Byron (Replat of Block 6, City of Byron).

1869 Thomas Hunter, Surveyor measured 1677' from the corner south to the center line of the railroad tracks.

5-1871 Robert Perry, County Surveyor,(Bk.A Pg.162 No.185) found a stone monument. Set witness stone 50 links west Meas. west 40.0 chs, to section corner 29-30-31-32. Found a stone at the 1/16 south to be .6 & 1/3 links east of a direct line to the south 1/4 corner 32 and a stone at the center 32 to be .4 & 1/4 links east of a direct line to the S 1/4 corner 32 (but on the E-W 1/2 line as run.) In survey no.186, Perry corrected the west 1/4 corner 32 10 & 3/4 links E and 24 1/2 links N. This would place the stone he found at the center 32 12 & 1/4 links south of the E-W 1/4 line.

6-12-1886 Thomas Hunter, County Surveyor, (Bk.A No.401 Pg.412 Old Filed Book 14 Pg.66) found stone planted in road in line of fence running west, and two rods east of west road fence witness stone to corner. He ran line south to a stone found at the S. 1/4 corner 32, however, he couldn't find the stone at the center 32.

7-1893 Willima Fraser, Deputy County Surveyor, (Bk.A Pg.525 No.490) found stone as given in City Plat and also stone 2 rods west. Drove piece of iron pipe down beside stone.

7-1927 county highway department (county highway department Bk.51 Pg.61) stone monument in place, also stone 33' west.

9-1933 John Kerr (Kerr Bk.9 Pg.3) dug up S 1/4 corner 29. Found it to be graded over deep so placed gears from ice cream freezer and a cast wagon skein on top same to bring near to top of the road. Measured 2633.8 east to fence on section line. (stone gone at section corner)

9-1936 The county highway department (county highway department Bk.84 Pg.1 & 72), iron pipe set for corner.

10-1939 John Kerr (Kerr Bk.16 Pg.40 & Bk.B Pg.520) shows iron over stone monument.

1949 county highway department (county highway department Bk.264 Pg.1) shows a spike in place at corner.

10-1962 county highway department (Cert. Filed) found wagon skein with 1" pipe on top. Set a CIM as the corner.

1964 John Kerr (Kerr Bk.88 Pg.65) used corner (no description) for a survey in the NE 1/4 section 32.

1974 County Surveyor measured from the CIM in place East to CIM at section corner 28-29-32-33, setting P.O.T. (nail) 465.93 east of 1/4 corner 29-32.

12-1982 County Surveyor found a 1" pipe in the new blacktop of CR 5. Found P.O.T. set 465.93 east in 1974 and the pipe checked on line from section corner 28-29-32-33 over the P.O.T. and 465.93 from the P.O.T. Accepted the pipe as perpetuation of the CIM location and left in place as corner.

7-22-1999 County Surveyor found pipe with plastic cap at surface CSAH #5 set 1" square pipe as reference and tied to corner.

9-22-1999 County Surveyor set p.k. nail at surface from ties taken in July.

6-9-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

5-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.