Certificate of Location of Government Corner

ID#: 752906 **Description:** 1/4 SEC COR 29 30 75 **Date Set:** 4/3/2013 **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.8'
The corner falls 4' east of fence north and in centerline of E-W twp road
Punch hole in top E end CMP NE 46.02'
Punch hole in top W end CMP NNE 32.08'
This corner is located by GPS reference stations "Ramen A & B"

Corner History:

6-1854 Gov't Notes Michael Karrick, Deputy Surveyor; North between sections 29 & 30. 40.00chs set quarter section post. RPs- 7" burr oak N 34° W 336 links, 10" burr oak S 78° E 225 links.

5-1871 Robert Perry, County Surveyor, (Bk.A No.185 Pg.162-167) located this 1/4 S by running from 25 (sec. corner 29-30-31-32 found original post on mound and set stone 4"x14"x23") to 43 (sec. corner 19-20-29-30). Setting it midway. No description of monument. He set the 1/64 south, a red elm post marked 1/64 south, stands in creek, and the 1/16 south, a stone 21"x13"x5". He also used the corner to set the 1/16 west and the center 30 and the center 29, all temporary points.

10-1939 John Kerr, County Surveyor, (Bk.B Pg.520, and Kerr Fieldbook 16 Pg.40) set 3/4"x30" bolt as 1/4 corner 29 & 30. Midway (2631.0') and on line between corner F (sec. corner 19-20-29-30 marked stone at fence corner) and E (sec. corner 29-30-31-32 stone at fence corner).

1964 John Kerr found 1/2" rod. Set CIM over a 1 1/2"x16" pipe at the rod location as the corner.

CORRECTION OF A CORNER: The correct corner is 5.25' North and 1.46' East of Kerr's CIM. (removed)

6-18-1970 County Surveyor remeasured line from sec. corner 19-20-29-30 (CIM over stone by Kerr in 1964) to sec. corner 29-30-31-32 (1 1/4 " iron pipe ,origin unknown). Found Kerr's CIM at 1/4 corner 29-30 was not midway and on line. Dug and found Kerr's 1939 bolt 5.25' north and 1.46' east of Kerr's CIM (removed). Didn't find anything else when digging. The Gov't corner here and Perry's corner couldn't be found so we accepted Kerr's 1939 bolt as the corner since it was set when the stones were in place at sec.cor. 19-20-29-30 and sec. corner 29-30-31-32. Set CIM over the bolt. The corner is .68' east of line between the section corners and .22' north of midway.

11-6-1982 County Surveyor found the CIM badly leaning. Dug down to bolt and reset CIM over it. Took new references.

8-6-1998 County Surveyor found CIM leaning badly in E-W Twp Road. Dug it out in pieces down to 7/8" bolt set in 1939. Set Cast Iron Cap on 6' long telspar pipe.

5-21-2002 County survey crew found telspar pipe with cast iron cap at the surface. Lowered 0.3'.

1-30-2009 County survey crew found telspar pipe w/no cap at surface leaning/bent easterly. Cut off top damaged portion of the pipe. Pipe is now down 0.2'.

3-16-2009 County survey crew found telspar pipe down 0.2' bent and leaning, removed.

4-3-2013 County survey crew set a 4' telspar pipe with cast iron cap at the previously measured GPS coordinate location.