Certificate of Location of Government Corner

ID#: 752909 **Description:** SEC CEN 29 75 **Date Set:** 11/7/82 **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe with cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 5 and in centerline of twp road west
Chiseled ">" in ring of manhole SE 64.70'
Chiseled">" in ring of manhole SW 73.11'
This corner is located by GPS measurement

Corner History:

5-15-1871 Robert Perry, County Surveyor, (Bk. A, No. 185, Pg.162-167 set a temporary point at intersecting 1/4 lines. Measured 40.06 1/2 chs. South to 1/4 corner 29-32. He also "set post in road" at the 1/64 South with a post .50 chs East and a stone 24"x14"x6" .50 West.

9-1936 county highway department (county highway department Bk.84, Pg. 72) found a "2"x6"x12" limestone about .9 west of line B-F (N-S 1/4 line section 29)". Measured South 2638.0 to iron pipe at 1/4 corner 29-32 and 2633.3 North to square iron nail at 1/4 corner 20-29 set midway and on line between stones found at the NE corner 29 and the NW corner 29.

10-1939 John Kerr, County Surveyor, (Bk. B, Pg. 520 and Kerr field book 16, Pg 40) ran E-W 1/4 line for road grading from the Center 29 West. He "found stone near fence corner as E 1/4 corner 29" and "set 3/4"x30" bolt as 1/4 corner 29-30 midway (2631.0) and on line between corner F (NW 29) and E (SW 29)" but "didn't see Center of section 29.

1974 county highway department (county highway department Bk. 378) found a 60D spike in intersection approx. 1' west of the centerline. Moved this point .83' West by putting the point on the tangent between the N 1/4 corner (as set this survey) and the S 1/4 corner section 29.

8-1974 County Surveyor dug for the center 29, but didn't find anything. Measured N-S and E-W 1/4 lines of section 29.

9-1974 McGhie & Betts set an iron rod at intesecting 1/4 lines.

2-2-1978 Zenk Engineering found and used 3/4" iron rod.

9-11-1978 McGhie & Betts found and used 3/4" iron rod.

6-12-1979 Yaggy Associates found and used 3/4" iron rod.

5-13-1980 County Surveyor took references to iron rod before road graded.

11-5-1980 county highway department (county highway department Bk. 406, Pg. 2) set 3/4" rod after road graded.

3-12-1981 county highway department set 5/8" iron rod with cap from references taken 5-13-1980. Removed county highway department iron which disagreed slightly with the County Surveyor's references.

1-18-1982 McGhie & Betts found and used monument.

11-7-1982 County Surveyor found 1/4 corner 29-30 to be badly leaning and measurements indicate it probably was when the iron was set at the Center 29 in 1974. After correcting the CIM at 1/4 corner 29-30, traversed the N-S and E-W 1/4 line of Section 29 and set a 1" square pipe with cap as Center 29 in new concrete of CR 5 at inter- secting 1/4 lines. Corner came .09' West and .08' South of corner referenced here 5-13-1980.

8-23-1985 V. Fangman found and used 1" square pipe w/cap.

9-17-1987 V. Fangman found and used 1" square pipe w/cap.

4-17-1989 McGhie & Betts found and used monument.

8-24-1989 V. Fangman found and used 1" square pipe w/cap.

5-25-1990 McGhie & Betts found and used 1" square pipe w/cap.

7-20-1991 V. Fangman found and used 1" square pipe w/cap.

4-19-1993 V. Fangman found and used 1" square pipe w/cap.

5-15-1996 V. Fangman found and used 1" square pipe w/cap.

3-13-1998 W. Claassen found and used 1" square pipe w/cap.

8-6-1998 County Surveyor found 1" square pipe w/cap at surface in centerline C.R. #5

3-16-2001 Brand & Massey found and used 1" square pipe w/cap.

5-20-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

7-8-2002 Brand & Massey found and used monument.

3-20-2003 Brand & Massey found and used 1" square pipe w/cap.

12-29-2003 Massey Land Surveying found and used 1" square pipe w/cap.

7-28-2005 Massey Land Surveying found and used monument.

10-23-2006 County Surveyor found 1" square pipe w/broken cap at surface in good condition. Replaced cap.