Certificate of Location of Government Corner

ID#: 753204 **Description:** S 1/4 SEC COR 32 75 **Date Set:** 6/9/2000 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 5, in centerline of township road west (Frontier Road SW) and 2' north of centerline of township road east (Frontier Road SE)
The monument is at the surface
County Survey Disc in PP NE 86.38'
Punch hole in N end 18" CMP NE 35.43'
Punch hole in S end 18" CMP SE 35.85'
Punch hole in S end 18" CMP SW 29.67'
Punch hole in N end 18" CMP NW 33.52'
Ref pipe NE 64.67'
This corner is located by GPS measurement

Corner History:

10-6-1853 John Ball, Deputy Surveyor, measured west 40.00 chains between Sections 32 and 5. Set quarter section post. Dug trench per instructions. RPs - 14" Black Oak West 45 links (29.70').

9-25-1856 E.P. Bircher, by Thomas Hunter, Deputy, (Old Road Book, Pages 28-29, Road No. 32 and New Road Book, Pages 117-118, Road No. 32), used quarter post for road survey.

4-20-1861 Samuel McDowell, (Book A, Page 66, Survey No. 93), used corner for property survey in the SE 1/4 Section 32 107-15 and NE 1/4 Section 5 106-15.

5-15-1871 Robert Perry, County Surveyor, (Book A, Pages 162-163, Survey No. 185), found stone monument averred placed where original mound and post stood. Tested stone with fence corner averred built 50 feet south and west of mound and post and found stone to be correct. RPs - 11" Black Oak N78°W 1.45 chains (95.70'), 14" Bur Oak N16°E 6.32 chains (417.12').

6-12-1886 Thomas Hunter, County Surveyor, (Book A, Page 412, Survey No. 401), found stone in center of cross roads.

7-25-1893 William Fraser, County Surveyor, (Book A, Page 525, Survey No. 490), found stone.

1952 County Highway Department, (CHD Book No. 203, Page 2), assumed corner. P.I. Sta. 0+00. RPs - Disc in fence corner post NE 48.3', Disc in telephone pole SE 48.2'.

8-17-1959 County Highway Department, (CHD Book No. 203, Page 2), updated ties for P.I. Sta. 0+00. RPs - Disc in telephone pole SE 44.32', Disc in fence corner post NE 48.17'.

1965 John Kerr, County Surveyor, (Reference Tie Book No. 1, Page 108), states 3/8" (5/8"?) rod in blacktop assumed by County Highway Department or McGhie & Betts, Inc. RPs - Nail & Disc in telephone pole SE 44.2', Nail & Disc in fence corner post NE 48.2', Bent spike in 18" Maple SW 48.75'.

8-31-1970 Roger Brand, County Surveyor, found 5/8" rod. Dug at the corner location and found the entire area had been dug previously. Believe stone and spot where it lay destroyed by previous diggings and construction. Accepted 5/8" rod as corner as it had been used by many surveyors.

4-8-1974 County Survey Crew set Cast Iron Monument over 5/8"x24"' rod at County Highway Department's 5/8" rod location. RPs - County Survey Disc in old power pole NE 86.38', Punch Hole in north end 18" CMP NE 35.43', Punch Hole in south end 18" CMP SE 35.85', Punch Hole in south end 18" CMP SW 29.67', Punch Hole in north end 18" CMP NW 33.52'.

7-19-1980 County Survey Crew found Cast Iron Monument in good condition.

6-4-1999 County Survey Crew found Cast Iron Monument down 0.4' in good condition. Set referernce pipe and tied out corner for bituminous overlay project and removed monument.

6-9-2000 County Survey Crew set 1" square pipe w/cap at surface at 1999 referenced location.

5-20-2002 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.