Certificate of Location of Government Corner

ID#: 753504 **Description:** S 1/4 SEC COR 35 75 **Date Set:** 2/11/2009 **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.1'
The corner falls 18' south of centerline of CSAH 34, in line with PP line north and 41 1/2' west of centerline of residential driveway north
County Survey Disk in SE side PP #19190 NE 89.78'
County Survey Disk in W side PP S 26.01'
Ref pipe NE 71.47'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick; 40.00 set quarter section post. RPs- 14" black oak N87° E 280 links, and 16" black oak S40°W108 links.

5-1877 Hunter Pg.360 No. 351; Corner gone, no evidence or knowledge. Set stone on town line 3x6x30 M & L 39.78 and bearing line south N20'E.

4-21-1965 J. Kerr set CIM from MHD stations and notes.

6-9-1970 County Surveyor removed CIM and checked rod below and set 1/2" rod in place of corner for road work. RPs- Hole in top of MN Hwy Dept R/W monument south 31.0-monument leaning north at least .4" on top sharp bank. Sta. 242+99.0, hard nail in knot on east side PP #39960 S 4.7', hard nail in knot on east side PP #40108 up 30" N 61.9', end of bolt in clamp of lower of 3 guy cables NE 98.91'.

NOTE: If using line from hilltop south west edge of either the brace pole top on south side of road or west edge of the big pole with 3 heavy insulators holding wires west near top will do for line south. RP to 1/2"rod-NE corner Hemp lands on true section line 1.17 south of south edge pavement, 1006.92 east of N 1/4 2, orange cap on SW side telephone cable pole, new pole SE 40.1', and 2" knot on SE side 9" green ash in yard 20" up NNE 71.85'.

7-6-1972 County Surveyor reset CIM from rod found below former CIM.

6-4-1992 County Surveyor found CIM leaning south. Dug CIM out and found 1/2" rod down 2.3'. RP-4.88' south to nail & plastic disc in PP #39960. Set (ref rod) 1/2" rod on edge of field; RPs- 57.0' north to centerline CR 34, 14.0' NE to south guy wire to PP #39960.

6-28-1993 County Surveyor set cast iron cap on telspar pipe on south shoulder CR 34 just in the blacktop set out from 1992 reference iron. RPs- Centerline CR 34 north 18.2', and plastic disc in PP #39960 south 4.89'. (tie was 4.88' in 1992)

8-12-2002 County Surveyor found cast iron cap on telspar pipe in good condition.

6-8-2006 County Surveyor found cast iron cap on telspar pipe at surface in good condition. Lowered corner down 0.2'.

9-5-2008 County Surveyor found cast iron cap on telspar pipe down 0.1' in good condition. Referenced corner for 2008 construction.

9-22-2008 County Surveyor removed cast iron cap on telspar pipe.

2-11-2009 County Surveyor set 4' telspar pipe w/Cast Iron Cap down 0.2' from 2008 overlay tie out.

8-24-2011 County survey crew found cast iron cap in good condition