Certificate of Location of Government Corner

ID#: 753505 **Description:** S SEC COR 34 35 75 **Date Set:** 2/11/2009 **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The monument is at the surface
The corner falls 16' north of centerline of CSAH 34
County Survey Disk in W side PP SW 72.98'
County Survey Disk in PP #40117 N 24.44'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: 80.00 set post and drove 15" charred stake to corner sections 2-3-34-35. Built mound with trench and planted SE osage orange seeds and NE apple seeds.

5-1879 T. Hunter Pg.360 No.351; Found stone center of road in line old fences. Averred by adjacent land owners as replacement of stake. 1/16 east set stone 2 1/2x8x24 M & L 19.89; measured South 39.35 to stone 5x8x15 replacing stake.

4-21-1965 J. Kerr set CIM by MHD notes.

6-8-1970 County Engineer removed CIMand checked rod below. Set 1/2" in place; RPs-hard nail west side PP #40117 N 24.6', punch mark in center rivet on west end field culv ENE 83.3', monument on south side road still in place. Station 216+69.

7-6-1972 County Surveyor found iron, reset corner with CIM and took additional refence points-hard nail in knot on north side guard post 3' north of west 17.94.

6-3-1992 County Surveyor found CIM in good condition. RPs-16.0' south to centerline of CR 34, 24.63' north to bottle cap in PP #40117. (Set 1/2" reference rod) RPs-±5' NW to middle guy wire, ±5' NE to east guy wire, 23.34' north to bottle cap in PP #40117.

6-28-1993 County Surveyor turned out June 1992 reference and set PK nail.

7-12-1993 County Surveyor set 10" CIM at surface of CR 34 over bottom half of old CIM in shoulder of CR 16' north of centerline.

8-12-2002 County Surveyor found CIM in good condition.

6-8-2006 County Surveyor found CIM at surface in good condition.

8-26-2008 County Surveyor found CIM down 0.1' in good condition. Referenced corner for 2008 construction.

9-22-2008 County Surveyor removed CIM. Found broken CIM down 1.1' in good condition and removed.

2-11-2009 County Surveyor set 1" square pipe w/cap at surface from 2008 overlay tie out.

8-24-2011 County survey crew found 1" square pipe with cap damaged. Replaced a new survey cap.