Certificate of Location of Government Corner

ID#: 753604 **Description:** S 1/4 SEC COR 36 75 **Date Set:** 2/12/2009 **County:** Olmsted

Section: 36 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is at the surface.
The corner falls in centerline of CSAH 34 and 69' east of centerline of field entrance north
Mn/DOT R/W monument S 50.04'
Ref pipe NW 84.20'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: John Ball, Deputy Surveyor; West between sections 1 & 36. 40.00 chs set post and drove charred stake, built mound with trench, and planted osage orange SE and apple seed NE.

2-1882 Thomas Hunter (Pg.375 No.366), County Surveyor, states corner gone, but Mr. Hinds avers a large cedar post was set on line and 2 rods south of original corner.

4-1902 Charles Armstrong (Pg.34 Bk.B), County Surveyor, found original stake in line with fence south.

7-2-1974 County Surveyor reset this corner using John Kerr's 2636.0' measurement from the east (BK.49 Pg.33) since when he measured there was a cross fence here (north & south) and used the center line of the road for north-south control. Set a railroad spike as the corner in the center line of CR 34.

6-4-1992 County Surveyor found RR spike in centerline of CR 34 in good cond. Set 1/2" rod reference. RP's 2.0' south to E-W fence 2.0' east to west gate post. Angle at ref rod. Angle RT S 1/4 36 to red light on KROC radio tower 43° 31' 49.5" to S 1/4 36 VA 90 24 59 dvol. SD 92.625 HD 92.62.

6-28-1993 County Surveyor set P.K. Nail from 1992 reference.

7-12-1993 County Surveyor set 5/8" re-rod w/cap as corner in centerline CR 34 at P.K. location set from ref on 6-28-93. RP's Mn/DOT R/W mon south 50.05'

8-12-2002 County Surveyor found rod w/cap at surface in good condition.

6-9-2006 County Surveyor found 5/8" rerod w/cap at surface in good condition.

2-5-2008 County Surveyor found 5/8" rerod w/cap at surface in good condition.

9-3-2008 County Surveyor found 5/8" rerod w/cap at surface in good condition. Referenced corner for 2008 construction.

9-19-2008 County Surveyor removed 5/8" rerod w/cap.

2-12-2009 County Surveyor set 1" square pipe w/cap at surface from 2008 overlay tie out.

8-24-2011 County survey crew found 1" square pipe in good condition.