Certificate of Location of Government Corner

ID#: 813505 **Description:** S SEC COR 34 35 81 **Date Set:** 6/21/1994 **County:** Wabasha

Section: 35 **Township:** 108N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Punched hole in SW end 18" CMP 7.90'
The corner falls at toe of slope in road ditch.
Post with sign is 0.5' south.

Corner History:

9-1853 Gov't Notes: Set post for corner. BT's: White Oak 8" N 41°E 6 links. White Oak 12" S 42°W 24 links. White Oak 12" N 25°W 45 links. White Oak 12" S 87-1/2°E 24 links.

10&11-1900 W.Fraser (P.69208 No.615) found stone Mr. Wells claims he set in place stake. Mr. Kimberly present both avered as to care in prop accuratly the former location of corner, left as is. 1/16 east "2" P.693 found stone in place proved to be 11 lks east and 1-1/2 lks south to be M&L 40.04 total. 1/64 east "3" P.693 found stone in place proved to be 16 lks east and 5-1/2 lks south to be M&L sec cor and 1/16 cor 20 rods east 4" P.693 found stone in place proved to be 16 lkis east and 4-1/2 lks south to be M&L left but used correct corner for survey. 1/16 south No.5 P.693 drove stake and set stone, set gov't prop. Plat shows 19.42 south then 19.92 to 1/4 cor. 1/64 south of No.5, No.6 P.693 drove stake marked M&L 9.96.

6-28-1977 Olmsted County Surveyor found 1-1/2" pipe with large disk on bottom (± 3' long pipe) sticking up 4". Dug down on east side of pipe and found limestone standing 4" x 5" x 24" with top 1.5 3-1/2' deep side of stone and set CIC/ 4-1/2 p2 over stone with top up ± 1.2' curve in road ± 10' below road grade level. RP: Outlet of 18" culvert (up 4') NE'ly 9.0

6-21-1994 Vince Fangman found 4' telspar leaning at 45° angle. This area was washed out and the corner was disturbed by a 2' x 2' x 1' chunk o f rip-rap for culvert. He cut the monument in half and reset by DNR coordinates which fit the location if stood up straight. He hit the previous mentioned stone when he got the monument flush w/ground. Larger chunks of limestone were piled around the southerly side of monument and the following ties were set: 7.70 to punched hole in SW end 18" CMP. 23.90 to 30d spk in 10" Elm SE. 38.35 to 30d spk in 6" Elm SW.

12-17-2009 County survey crew found cast iron cap on telspar pipe down 1.5' in good condition.