Certificate of Location of Government Corner

ID#: 830504 **Description:** 1/4 SEC COR 5 8 83 **Date Set:** 6/27/79 **County:** Olmsted

Section: 05 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 8' south of centerline of E-W twp road and 1' west of fence north
County Survey Disk in E side PP #47179 NNE 42.17'
Large nail in top CP S 24.72'
1/2" pipe N 50.01'
Post w/sign 23' south
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes W.B. Yerby, Deputy Surveyor West on true line between sections 5 and 8. 40.025 chs. Set a charred quarter section post in mound of earth and sod and made trench and pits. Planted Osage orange seed on east and west sides of trench. 80.05 chs. To section corner.

7-1867 H.E. Horton surveyed Farmington Cemetery in the NW 1/4 Sec. 8. The north line of the cemetery is 33' south of and parallel to the north line of the NW 1/4 Sec. 8.

10-1883 Thomas Hunter, County Surveyor, surveyed the First Addition to the Farmington Cemetery in the NW 1/4 Sec. 8. The north line of the cemetery is 33' south of and parallel to the north line of the NW 1/4 Sec. 8.

9-1966 John Kerr, County Surveyor, (Kerr Book 94, Pages 59-60) dug in line with the fences north and south and on line from a point in the centerline of T.H. 63 and in line with the fence west at Sec. Cor. 5-6-7-8 over a point 33' north of the north line of the Farmington Cemetery. Found the remains of a stake down in clean yellow clay. Set a 1/2" steel through the stake and placed a C.I.M. over it. RPs- corner lies withing 2' of south edge traveled road, corner lies 1' west of fences N & S, nail in top new creosote corner post S 24.72'.

6-27-1979 County Surveyor found Kerr's C.I.M. with the head broken off and deep in road. Broke off two more sections of the C.I.M. and set a new C.I.M. over the remainder and up to the surface of the road. RPs-1/2" pipe under fence North 50.01' North 50.0', C.S.D. in East side power pole NNE 42.17'
C.I.M. 1' West of fences North centerline South, Large nail in top corner fence post South 24.72', M.H.D. disc in NW side 3" plum (up 5') SW 32.86'.

10-18-2007 County Surveyor found CIM down 0.6' in good condition.