Certificate of Location of Government Corner

ID#: 832606 **Description:** 1/4 SEC COR 26 27 83 **Date Set:** 7/14/1994 **County:** Olmsted

Section: 26 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11 and in line with fences east and west
The monument is down 1'
Punch hole in N end 18" CMP NW 40.37'
County Survey Disc in CP E 50.18'
Ref pipe E 38.02'
This corner is located by GPS measurement

Corner History:

5-17-1854 William B. Yerby, Deputy Surveyor, measured north 40.00 chains between Sections 26 and 27. Set quarter section post in mound of earth and sod, deposited charcoal. Made trench and pits, planted Osage Orange seed east and west.

10-15-1946 John Kerr, County Surveyor, (Book C, Page 50 and Kerr Field Book 32, Pages 27-29), set 3/4"x10" pipe over 3/8"x36" pipe midway and on line at 2643.71'.

7-6-1983 County Survey Crew dug and found 3/4" pipe over 3/8" pipe down 2' in good condition. Remove pipes and dug down 7' to clean clay. Conditions excellent but found nothing further.

8-4-1983 County Survey Crew set Cast Iron Cap on telspar pipe as corner on line between the section corners and in line with fences east and west. The corner falls 0.70' east of Kerr's pipe location. The corner falls 1/2' west of centerline CSAH 11. RPs - Punch hole in south end 18" CMP W 30.95', Punch hole in north end 18" CMP NW 40.37', CSD in corner post E 50.06'.

7-30-1993 County Survey Crew found Cast Iron Cap on telspar pipe at surface in good condition. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. Removed monument.

7-14-1994 County Survey Crew set 1" square pipe w/cap at surface at 1993 referenced location. The corner falls in centerline CSAH 11 and in line with fence east. RPs - Punch hole in 18" CMP NW 40.37', County Survey Disc in leaning corner post E 50.18'.

3-12-2007 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.

5-24-2011 County Survey Crew found 1" square pipe w/cap at surface in good condition. Drove pipe down below bituminous prior to road surface milling and overlay.