Certificate of Location of Government Corner

ID#: 833104 **Description:** S 1/4 SEC COR 31 83 **Date Set:** 10/10/2012 **County:** Olmsted

Section: 31 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The monument is at the surface
The corner falls 1 1/2' north of centerline of CSAH 14 and 8' east of centerline of Dresser Dr NE
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Ball, Deputy Surveyor West between sections 6 and 31. 40.00 chs. Set post and drove charred stake. Built mound with trench and planted osage orange seed S.E. and apple seed N.E. 77.66 chs. To township corner.

7-1917 John Kerr (Book B, Page 268), found stone.

1957 County Highway Department (Bk. 95 P.11) set rod at corner on line from pipe at S.W. Cor. Sec. 31 to stone at S.E. Cor. Sec. 31 and at John Kerr's 1917 measure from S.W. 31.

1958 John Kerr (Bk. 73 P. 56) found rod. Accepted as corner.

1963 John Kerr in Bk. 87, P. 50-52, records iron at corner.

CORRECTION OF CORNER: Correct corner lies 4.83' E. and .35' N. of rod recorded as corner by John Kerr in 1958 (rod removed).

5-18-1976 County Surveyor dug and found 5"x5" / 16"x15" limestone 20" deep with base in clay. Corner 4.8' E. of centerline of road S. and 1' N. of centerline E-W road. Set scrap iron around stone and C.I.M. over stone. Stone lies 4.83' E. and .35' N. of County Highway Department rod (removed). RPs-Correct corner lies 4.83' E. and .35' N. of rod recorded as corner by John Kerr in 1958 (rod removed), Punch hole top N. end C.M.P. W.N.W. 120.23', Punch hole top S. end C.M.P. W.S.W. 121.94' , Bottom bolt of pair on s. side of power pole #39798 S.W. 198.92' ,C.S.D. W. side of power pole #34584 S.E. 138.27'.

12-4-1996 County Surveyor found C.I.M. in good condition 4" deep in CSAH #14.

12-16-1997 McGhie & Betts found CIM 1' North of centerline of County Rd. 14 and checked the references.

6-14-1999 County Surveyor found CIM down 0.3'. Set ref pipe and tied out corner and removed CIM

6-8-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

11-15-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

10-19-2010 Brian Veronen, MNDOT LSIT, found 1" square pipe with cap in good condition and checked ties.

10-10-2012 The monument was destroyed by road construction of the Hwy 63 roundabout intersection. Olmsted County survey crew set a new 1" square pipe at the previously measured coordinate location.