# Certificate of Location of Government Corner

**ID#:** 833504 **Description:** S 1/4 SEC COR 35 83 **Date Set:** 10/27/2005 **County:** Olmsted

**Section:** 35 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 13' north of centerline of E-W twp road and 3' west of fence south
1/2" rod in fence S 99.95'
County Survey Disk in N side PP #33161 (up 6') NW 35.15'
This corner is located by GPS measurement

**Corner History:**

10-1853 John Ball. 11.90 Brook 3 lks. Wide Bears North. 40.00 Set post for quarter section corner.
Burr Oak 6 N88E 670 lks. Burr Oak 10 N80W 280 lks. 60.00 leave openings and enter prairie bears NE.
69.20 Brook 3 links wide bears NE.

5-1872 T. Hunter, P.202, No.211 corner missing NE Bearing tree cut, other Bearing tree standing set temp stake from Bearing Tree for line south. No measure.

7-1966 J. Kerr, corner could not be in place. Deep ravine just north of road in area of corner deep fresh fill.
Run and measure line from SW35 to S1/4 36 from east. Misjudged line so random came over 2 rods south at west end. This bringing corner at S1/4 35 3' off road on north side traveled road in soft fill. Corner placed a 1/2"x4' rod on M&L 2630.85'. Corner lies 3' west of fence running south. Drove 1/2"x3' rod up 3' on west side fence S 100.0'. Disc south side large trans power line ENE 178.8'. 4' rod may not stay in soft new fill, CIM would never.

10-27-2005 County Surveyor found 5/8" pipe down 0.9' leaning north. Found 1/2' rod up 0.2' in fence line south. Pulled 100' from rod and determined pipe was leaning 0.25' north. All other ties gone or destroyed. Set 5' telspar w/CIC down 0.3' from E-W tie taken from pipe and N-S tie taken from 1/2' rod. CSD w/60d nail in north side of PP #33161 up 6.0' NW 35.15' and 1/2' rod .6' west of N-S fence south 99.95'.