Certificate of Location of Government Corner

ID#: 840104 **Description:** 1/4 SEC COR 1 12 84 **Date Set:** 10/5/90 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 15' NW of centerline of CR 114 and 29 1/2' NE of centerline of field drive NW
40d in 24" Oak S 89.42'
Chiseled holes in N end CMP W 23.32'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes, Michael Karrick, Deputy Surveyor West on true line between sections 1 and 12 40.00 chs. Set quarter section post 8" bur oak N27°E 25 10" bur oak S12°E 37 lks.

5-1879 Thomas Hunter, County Surveyor (Pg. 359, No. 350) Found stone planted in ground in place of original quarter post when standing, set by Mr. Miller and other. Bearing trees cut and grubbed out. Chained west 39.67, chained north 19.78 1/2 set stake then 19.78 1/2 to center of section 1, set at intersecting quarter lines.

8-1964 John Kerr, County Surveyor (bk 88, Pg. 27) Corner gone, destroyed by road work. Set 1/2" rod on line from north quarter of section 1 over center of section 1 and 5168.44' from quarter corner 12, 13. Rod fell in west road ditch and near field drive.

1-10-74 County Surveyor set P.K. nail from ties taken in 1964, could not find 1/2" rod, but ground frozen, did not dig.

7-18-90 County Surveyor could not find P.K. nail set in 1974, but dug and found 1/2" rod set in 1964 down 1.2' on westly shoulder of road.

10-5-90 County Surveyor set telspar pipe with cast iron cap in place of 1/2" rod set in 1964.

4-22-2004 County Surveyor found cast iron cap on telspar pipe down 0.7' in good condition.

7-25-2005 County Surveyor found cast iron cap on telspar pipe down 0.7' in good condition.

1-5-2006 County Surveyor found cast iron cap on telspar pipe down 0.7' in good condition.