Certificate of Location of Government Corner

ID#: 840507 **Description:** N SEC COR 5 6 84 **Date Set:** 9/30/2002 **County:** Olmsted

Section: 05 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 10' south of centerline of E-W twp road and 9' west of fence south
The monument is down 0.5'
Pop can in top of brace post SE 28.89'
County Survey Disk in PP #52771 ESE 82.98'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, M.Karrick; 80.0 Intersected Standard Parallel No.2 955 links east of 1/4 section post in south boundary at section 31 of twp 109. Set section post to section 5 & 6 and erected mound of trench, pits, charred stake and osage orange seeds at each angle.

9-1893 W.Fraser Pg.533 No.496; Corner gone and no evidence of corner or how to relocate it. Set stone 5x8x18 on line and gov't porp. Meas.

6-1894 W.Fraser Pg.550 No.508; found corner. Set 16 east, west, and center NW 1/4 5.

6-1969 J.Kerr set CIM over 1/2" rod with china, cans, and glass. RPs- M.Dew cap in top 4" cedar brace post SE 28.95, corner on extreme south edge of traveled road.

4-1983 Olmsted County Surveyor found CIM tilted south and on reference point left. Reset CIM over 1/2" rod. Corner 8' south of centerline E-W road and 9' west of fence line south. RP- pop can in top of brace post SE 28.95'.

9-30-2002 Olmsted County Survey Crew found CIM down 1.2' with head broken and leaning South. Removed CIM found 1/2 iron rod down 2.3'. Set 5' telspar w/CIC over iron rod down 0.4'. Set CSD in PP #52771 ESE 82.98'.

5-6-2010 Olmsted County survey crew found CIC on square pipe down 0.4' in good condition.

2-26-2010 Rudy Martin, MN/DOT Crew Chief, found CIC on Telspar pipe in good condition.

6-14-2011 County survey crew found cast iron cap on telspar pipe at surface in good condition. Drove it down 0.5'.