Certificate of Location of Government Corner

ID#: 840906 **Description:** 1/4 SEC COR 8 9 84 **Date Set:** 3/25/2002 **County:** Olmsted

Section: 09 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 12 and 1' west of centerline of CSAH 27
County highway disk in PP NE 84.28'
Punch hole in W end CMP S 50.80'
Punch hole in E end CMP ESE 64.12'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, M.Karrick; 40.0 set 1/4 section post in mound wih trench, pits, charred stake and osage orange seeds NE & SW.

5-1892 T.Fraser Pg.485 No.462 S 8; Set iron stake as corner.

NOTE: Plat in record shows north & south 39.87 1/6.

1939 county highway department Field Bk.113 Pg.77; found 1" iron rod. RPs- hub in fence line SSE 96.1, spike in tlel pole SW 50.5. Iron stake as corner many years. Many mixed uo RPs county, J.Kerr, and McGhie. RPs-hub in fence south 96.1, spike in pp ENE 129.0, spud in fence corner SE 46.15, spike in tele pole SE 64.15.

1964 county highway department Bk.297; Found 1" pipe.

4-24-1969 J. Kerr found iron pipe. Set short CIM. RPs- disc tele pole SW 64.15, disc tele pole SE 91.25, disc in trans pp# 37984 ENE 127.75, 1/2" pipe in ditch south S 33.32, disc in leaning corner fence post SE 47.0.

7-17-1985 County Surveyor took transit ties to corner before road const.

10-25-1988 County Surveyor set telspar pipe/C.I.C. from transit ties.

6-6-2001 County Surveyor found cast iron cap on telspar pipe at surface in good condition

6-19-2001 County Surveyor set 1" square pipe w/cap as ref pipe for 2001 overlays. Tied out corner and removed cast iron cap on telspar pipe.

9-21-2001 County Surveyor set pk nail at surface from 2001 overlay tie out.

3-25-2002 County Surveyor set 1" square pipe w/cap at surface from ties taken from ref. pipe.

12-3-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

7-26-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.

11-7-2011 Mike Hendrickson, MNDOT Crew Chief, found 1" square pipe with cap RLS #15809 in good condition and updated the reference ties.