Certificate of Location of Government Corner

ID#: 841905 **Description:** W SEC COR 19 30 84 **Date Set:** 5/1/1975 **County:** Olmsted

Section: 19 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of N-S twp road and 2' south of fence west
120d spike in huge Elm ENE 45.05'
60d nail in NE side 12" blazed Burr Oak SSW 133.0'
20d nail in top of 5th wood fence post north of CP NW 68.12'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: Karrick, Deputy Surveyor; On true line between sections 19-30. 38.22 chs. Set quarter section post. RPs- 8" aspen S85°W 40 links, 10" aspen N45°W 60 links, 10" aspen S9°E 76 links, 12"aspen N70°E 78 links.

4-1871 R. Perry by T. Hunter Pg.181 No.192; Found stake and tested bearing trees. Meas. West and north.

5-1881 T. Fraser Pg.446 No.431; Accepted fence corner post as corner after testing with bearing tree stumps. Set stake on NE side.

1-1892 Thomas Fraser Pg.468 No.450; Found corner. Reset Pg.446 post of fences S,E,W.

5-1899 R.Frasesr Pg.642 No.578; Found post and stake recorded in former survey and spot 1' south which could have been gov't stake or where it originally stood. No measure.

1919 Dave Williams pg. 213 B ran line NW corner 19 to SW 30 and set limestone with cross and 2 horseshoes under it. RPs- 6" oak N63°45'W72', 12" burr oak S71°E 45.7'. Found old stake by corner post running deep.

1935 county highway department Bk.86 Pg.78, found limestone over horseshoes.

1942 J.Kerr Bk.27 Pg.13; Run line as in Pg.217 NW 19 to SW 30. Set rod and referenced at 5248.85 M & L.

7-1964 J. Kerr set CIM over 3/4"x12" rod. RPs- 18" oak stump N84°W 61.9, drag tooth in 15" pin oak S40°W 80.25, 120D in 20" elm E 45.45.

5-1973 County Surveyor removed CIM and iron rod. Set square head bridge bolt. RPs- 68.12 NW to head of 20D nail in top 5th wood post, 133.0 SSW to 60D on NE side up 1' 12" blazed burr oak, 45.05 10' N of E to 120D in elm.

11-29-1973 County Surveyor found iron bolt. Set CIM above bolt.

5-1975 County Surveyor dug entire road and found nothing. Reset corner on line and at Gov't proportionate measurement.

12-4-2002 County Surveyor found CIM down 0.9' in good condition.