Location of Center of Section

ID#: 842409 **Description:** SEC CEN 24 84 **Date Set:** **County:** Olmsted

Section: 24 **Township:** 108N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

County Surveyor recommends using the computed intersection of quarter lines for the center of section.

Reference Ties:

The corner falls 13' west of centerline of township road (11th Ave NE) and near abandoned driveway
60d spike in 20" Oak NE 36.77'
County Survey Disc in 15" blazed Oak NW 32.59'
County Survey Disc in east side 24" Oak NNW 46.54'
County Survey Disc in round gate post for fence east W 62.90'
1" square pipe, "Combine A", SE 40.48'
This corner is located by GPS reference stations "Combine A & B"

Corner History:

5-8-1877 Thomas Hunter, County Surveyor, (Book A, Page 308, Survey No. 302), set 10"x12"x18" boulder at intersecting quarter lines. 1/16th South set stake with stone by its side midway and on line at 19.86 chains (1310.76'). 1/16th East set stake midway and on line at 19.93-1/4 chains (1315.55'). 1/16th West stake midway and on line at 19.91-1/2 chains (1314.39'). 1/16th Center of NE 1/4 set stake midway and on line at 19.81 chains (1307.46') on the north-south sixteenth line. 1/16th Center of SW 1/4 set stake at intersecting sixteenth lines. 1/16th Center of SE 1/4 set 7"x8"x20" stone at intersecting sixteenth lines.

8-28-1972 Roger Brand, County Surveyor, dug but found nothing. 1/16th South dug and found 3"x8"x14" stone down ±6'. Set 1/2" rod at surface. Set 1/2" rod on line and at double the distance from South quarter Section 24 over the 1/16th South of Center. The corner falls 3-1/2' south of fences east and west. RPs - 60d spike in 24" Oak ENE 36.7', NW edge telephone cable post SW 42.3'.

6-1-1976 County Surveyor dug again to cover Thomas Hunter's full measure from East quarter corner. Found nothing.

4-28-1978 County Surveyor dug again but found nothing. 1/16th East dug and found small wood pieces. 1/16th West dug and found dark spot in clay. Set Cast Iron Cap on telspar pipe on east-west quarter line at prorated Thomas Hunter measure. The corner falls 11' west of centerline of township road and in line with fences east and west. RPs - County Survey Disc in 15" blazed oak NW 32.59', Center corner post W 25.6', 60d spike in 20" oak NE 36.77', Center leaning corner post E 37.5'.

10-27-1982 McGhie & Betts, Inc. found and used Cast Iron Cap on telspar pipe at intersecting quarter lines.

12-19-1987 Land Consultants used computed center at intersecting quarter lines.

7-30-1993 Ed Kuisle, County Surveyor, used Cast Iron Cap on telspar pipe at intersecting quarter lines. The corner falls 12-1/2' west of centerline of township road.

6-3-2005 Fangman Land Surveying set 1/2" pipe w/cap #14888 over broken Cast Iron Cap on telspar pipe at intersecting quarter lines.

10-28-2005 County Survey Crew found 1/2" pipe w/cap #14888 down 0.3'. Took local ties and removed. Found broken Cast Iron Cap on telspar pipe down 0.8' leaning north. Took local ties and removed. Found nothing below. Set GPS reference stations "Combine A & B" and measured their positions using GPS. RPs - 1" square pipe, "Combine A", SE 40.48', 1" square pipe, "Combine B", S 399.70'.

6-6-2006 Fangman Land Surveying found and used 1/2" pipe w/cap at intersecting quarter lines.

1-26-2007 County Survey Crew set Cast Iron Cap on 4' telspar pipe down 0.4' at intersecting quarter lines. The corner falls 13' west of centerline of township road (11th Ave NE). RPs - County Survey Disc in east side 24" Oak NNW 46.54', County Survey Disc in round gate post for fence east W 62.90'.

8-21-2008 McGhie & Betts, Inc. found and used Cast Iron Cap on telspar pipe at intersecting quarter lines.

8-27-2008 Fangman Land Surveying found and used Cast Iron Cap on telspar pipe at intersecting quarter lines.

8-25-2011 County Survey Crew found Cast Iron Cap on telspar pipe down 0.3' in good condition.

11-6-2026 County Survey Crew found Cast Iron Cap on telspar pipe down 0.5' bent south. Removed monument.