Certificate of Location of Government Corner

ID#: 842704 **Description:** 1/4 SEC COR 27 34 84 **Date Set:** 11/2/2006 **County:** Olmsted

Section: 27 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 112 and in centerline of CR 154 west
County Survey Disk in SE side PP #24433 NE 54.36'
County Survey Disk in NE side PP NW 56.62'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes, Michael Karrick, Deputy Surveyor West on true line between sections 27 and 34 40.00 chs. Set quarter section post in mound with trench, pitts charred stake and osage orange seeds NE and SW.

6-1867 H.E. Horton (Pg. 85, No. 131) used corner chained west 19.94 1/2 then 19.94 1/2 to section corner.

6-1884 Thomas Hunter, County Surveyor (Pg. 390 No. 381) corner missing, dug for corner found nothing. Found sixteenth stone set by H.E. Horton in 1867. Set stake for quarter corner 27,34 from section corner 27, 28, 33, 34 over sixteenth stone found 19.95 chs. then 19.95 chs.

3-1896 William Fraser, County Surveyor (Pg. 592, No. 538) didn't look for corner used sixteenth stone west chained 10.97 1/4 set stake then 8.97 3/4 chs. to section corner.

10-1913 D. Williams, County Surveyor (Pg. 240, bk B) Found boulder with post 3' high beside it and small stones in crossroads. Measured south 2653.3' to center of section 34 set at intersecting quarter lines a stone.

1941 Power line survey measured 2652.5 south to center of section 34.

9-1963 John Kerr, County Surveyor found stone set cast iron monument over stone and iron.

1968 county highway department (bk 326) found cast iron monument took ties. RPs- spike in pp NE 50.5, spike in tele pole SE 59.7, spike & disc in pp NW 39.9, spike & disc in brace pole SW 52.7.

8-21-1969 County Surveyor removed cast iron monument before road construction set 3/4" rod on hilltop west took transit ties.

7-6-1970 county highway department Set 3/4" rod took ties. RPs- spike & disc in pp NW 56.32, spike & disc in brace pole SW 65.52, spike & disc in pp NE 54.46.

8-28-1974 County Surveyor reran the north line of section 34 and set the corner 8.82' north of the line between section corners as John Kerr referred to when he found the stone and used 3/4" rod transit tie for east control. This point fell 0.28' east of county highway department 3/4" rod set in 1974. Removed same and set RR spike at our point. RPs- county highway department disc in NE side of pp# 41290 NW 56.44, CHS disc N side of pp# 36675 SW 65.89, CSD SE side of pp# 41074 NE 54.08.

4-6-90 County Surveyor dug down 5" in new blacktop found RR spike, removed and set 1" square pipe/cap in its place flush with blacktop. RPs-C.S.D. in P.P. #43191 NW 66.54', C.S.D. in P.P. #50637 SW 68.50', C.S.D. in P.P. #41074 NE 54.30'.

1-22-2003 County Surveyor found 1" square pipe w/cap in good condition at surface.

2-2-2006 County Surveyor found 1" square pipe w/cap in good condition at surface. Set reference pt and tied out corner for 2006 overlays.

4-3-2006 County Surveyor found 1" square pipe w/cap at surface in good conditon.

11-2-2006 County Surveyor set 1" square pipe w/cap at surface from 2006 overlay tie-out.