Certificate of Location of Government Corner

ID#: 842705 **Description:** SEC COR 27 28 33 34 84 **Date Set:** 6/10/1999 **County:** Olmsted

Section: 27 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 154 and 92 1/2' west of centerline of field drive north
County Survey Disk in PP NE 93.72'
County Survey Disk in SE side brace post NE 96.44'
County Survey Disk in NE side 18" Walnut stump SE 48.03'
County Survey Disk in W side 24" Maple N 79.09'
5/8" rerod in pasture SE 99.92'
Ref. pipe (STA Landfill) ESE 90.65'
This corner is located by GPS measurement

Corner History:

1854 Gov't notes, M.Karrick; 80.0 set a post for corner to section 27-28-33-34 and erected mound with trench, pits, charred stake and osage orange seeds at each angle.

6-1867 H.E. Horton, County Surveyor, (Book A, P.85, No.131) used this corner to set the 1/16 South and the 1/16 East.

6-1854 Gov't Notes: Michael Karrick, Deputy Surveyor North between sections 33 and 34. 80.00 chs. Set post for corner to Sections 27-28-33-34. Erected mound with trench, pits, charred stake, and Osage Orange seeds at each angle.

6-1884 Thomas Hunter, (Book A, Page 390, No. 381), County Surveyor, found a stone in the center of the road set by a Mr. Vroman and others interested in the mound when the corner stood.

3-1896 William Fraser (Book A, Page 592, No. 538), County Surveyor, found the stone P. 390.

10-1913 Dave Williams (Book B, Page 240), County Surveyor, found two stones in the South wheel track. Took bearing trees: Cottonwood S.W. 57.4 and Walnut S.E. 48.

9-1966 John Kerr, County Surveyor, found the probable bearing trees P. 240. Dug and found a stake with 2 stones and smaller rocks. Set a C.I.M. over a 3/4" x 2' pipe as the corner. RPs- 20D south side 48" cottonwood AZ233.15 SW 58.7, 20D east side 18" cottonwood AZ 134°45 SE 48.0, disc in NE side pp AZ303°45 NW 39.08.

5-10-1972 County Surveyor removed the C.I.M. for road grading and replaced it with a 1/2" iron rod and took references.

8-29-1974 County Surveyor found a 60d spike which checked correct by the references.

9-29-1977 County Surveyor found the nail used in 1974 badly bent so dug down to Kerr's pipe still in place. The rod set in 1972 was also badly bent so removed it. Set a C.I.M. over the pipe. RPs- Corner in centerline E-W road and in line with east end of quanset to south, 5/8"x2' rod set in pasture SE 99.92, 46.50' south of center of road east and on line to tower in distance. 5/8"x2' rod set in pasture SE 99.92

5-29-1981 County Surveyor found the C.I.M. set 9-29-1977 tilted West. Dug down to Kerr's pipe and reset the C.I.M. over the pipe. RPs-5/8"x2' rod set in pasture SE 99.92, spike & disc in NE side 18" walnut SE 48.03, spike & disc in W side 24" maple N79.09, CSD disc on SE side of brace post on W side of driveway N NE 96.44.

6-4-1998 County Surveyor found CIM in good condition 25" deep in new grade. Referenced corner before cold recycling bituminous surface of C.R. #154.

6-10-1999 County Surveyor set 1" square pipe w/cap at surface.

3-8-2001 Mn/DOT Survey Crew found corner in good condition.

12-3-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.