Certificate of Location of Government Corner

ID#: 842904 **Description:** 1/4 SEC COR 29 32 84 **Date Set:** 8/26/2011 **County:** Olmsted

Section: 29 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' north of centerline of E-W twp road and 11' west of fence north
Punch hole in E end 18" CMP NE 37.77'
Punch hole in W end 18" CMP NNW 28.00'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick, Deputy Surveyor West between sections 29 and 32. 40.00 Set quarter section post in mound with trench and pits and charred stake and planted Osage Orange seeds N.E. and S.W. 80.00 To section corner.

5-1873 Thomas Hunter (P. 224 No. 227), County Surveyor, found long granite stone in center of road.

7-1-1902 Robert Fraser (old fieldbook #10 P. 50-51), County Surveyor, could find nothing.

7-1966 John Kerr, County Surveyor, ran and measured line from N.E. 32 to N.W. 32 and set a 1/2" rod on true line. West 1/2 mile=2627.7' and East 1/2 mile=2629.6'. Dug 12' x 20' but found nothing. RPs- steel angle corner post NE 35.8, corner lies 10.9' west of fence running north and 25.8' north of fence running E & W.

7-22-1970 County Surveyor decided to leave rod as is as corner.

4-20-1973 County Surveyor found 1/2"x30" iron. Road to be graded so corner rod removed and reference rod set. RP- 1/2"x30" rod 10' E of N 70' under fence down 10".

4-11-1975 County Surveyor set CIM over 5/8"x9" rod. RPs- punch hole W end 18" CMP 3' W of N 28.02', punch hole E end 18" CMP NE 37.78, 1/2" rod under fence NNE 69.37', corner falls 2 1/2' north of centerline E-W twp road and 10 1/2' west of fence line running north.

6-4-1998 County Surveyor found CIM with head missing 12" deep in crushed rock twp road 2' north of centerline & 11' west of fence north.

3-7-2001 Mn/DOT Survey Crew found monument with head missing.

4-2-2001 County Surveyor found CIM down 0.8' with head missing in good condition.

7-10-2003 County Surveyor found CIM with head missing down 1' in good condition. Set 2 pts to tie-out corner for Hwy 52 construction.

9-27-2004 Mn/DOT Survey Crew found monument with head broken off down 1'.

12-13-2004 County Surveyor found CIM with head broken off down 1' in good condition. Pulled monument and set cast iron cap on telspar pipe as corner.

8-26-2011 County survey crew searched for but could not find telspar pipe. It was likely buried or destroyed by the construction of a nearby bridge. Set 4' telspar pipe with cast iron cap using previously measured GPS coordinates.