Certificate of Location of Government Corner

ID#: 843006 **Description:** W 1/4 SEC COR 30 84 **Date Set:** 4/11/75 **County:** Olmsted

Section: 30 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of N-S twp road and 1' north of centerline of twp road east
Spike in S side 10" Walnut SW 77.66'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: Ball, Deputy Surveyor; North between sections 25 & 30. 40.0 chs. Set post for quarter section corner. RPs- 6" black oak S7°E 14 links, 5" black oak N55°W 14 links

2-1882 Thomas Hunter (Pg.374 No.365) County Surveyor states stake and bearing trees gone. Found and accepted stone claimed set where original corner stood.

10-1890 Thomas Fraser Pg.446 No.431, County Surveyor states stone gone. Set boulder midway and on line.

6-1899 Robert Fraser Pg.642 No.578, found boulder. Drove iron stake beside boulder. RPs- burr oak N51° E56 links, 8 1/2 paces east of west road fence running N & S.

1942 John Kerr Bk.27 Pg.13, County Surveyor set pipe & 1/2" rod and set CIM over 3/4" rod. RPs- spike tele pole NE 57.2, spike 20" maple NW 43.8, center 24" burr oak ENE 125.0, fence line west S 6.4.

1960 Kerr Bk.80 Pg.52, set temporary nail midway and on line.

7-1964 Kerr found pipe and 1/2" rod. Set CIM over 3/4" rod. RPs- spike in telephone pole NE 57.2, spike in 20" maple NW 43.8, fence line west S 6.4, center 24" burr oak ENE 125.0.

5-1973 County Surveyor found stake hole 4.25' south and .05' ± east from Kerr's CIM. Drove 1/2" rod over old TV chassis in hole with botle neck in stake hole.

12-1973 County Surveyor remeasured west line of section 30 electronic.

4-11-1975 County Surveyor removed CIM and reset the corner midway and on line as per Thomas Fraser at 2617.93'. Corner comes .23' east and .96' south from stake hole and 5.22' south and .2'± east of Kerr's corner location. Set CIM over a 5/8"x10" rod. RPs-SE corner telephone box 131.23', spike on south side 10" walnut 77.66', CSD disc on SW side pp# 23977 97.79', THIS IS C CORRECTION OF A CORNER: Corner lies 5.22' south and .2'± east of Kerr's corner location.

12-4-2002 County Surveyor found CIM down 0.9' in good condition.