Certificate of Location of Government Corner

ID#: 843305 **Description:** S SEC COR 32 33 84 **Date Set:** 5/26/2005 **County:** Olmsted

Section: 33 **Township:** 108N **Range:** 14W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The monument is at the surface
The corner falls 1' south of centerline of center median on CSAH 14, 5 1/2' east of line of N-S catch basins and 1 1/2' west of fence south
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, John Ball, Deputy Surveyor, West between sections 4 and 33. 80.00 chs. Set post and drove charred stake for corner. Built mound with trench and planted osage orange S.E. and apple seed N.E.

5-1874 Thomas Hunter (P. 249 No. 250), County Surveyor, could find no trace of the corner, but a Mr. Beneke avered his fence south was built exactly on line and his corner post at the road line was exactly 2 rods South of the stake when standing. Hunter drove a stake in the center of the road in line of the old fence and 2 rods North of the South road fence.

7-1-1902 Robert Fraser, (Old Field Book 10 P. 50-51) found an old stake on the south side of the road. Put a boulder stone in place of the stake and on top of the bottom of the stake.

10-1913 Dave Williams (P. 240B), County Surveyor, found a 10"x14" boulder with a rotted stake by its side in the grass at the side of the road and 33' North and South of the fences and 2'East of the fence south.

1930 County Highway Department (loose notes in B. 63) records a 2" x 2" hub over a stone 12" deep.

1961 County Highway Department (B. 234 P. 4) records a concrete monument with a 7/8" rod riser. RPs- disc in corner fence post S, disc in corner fence post SW, disc in pp SW 62.03.

6-1-1977 County Surveyor dug with the backhoe. Found a small iron over a concrete County Highway Department monument over a long bolt. Dug further and found a 10"x12"x18" boulder 7' deep over a stake. There was also a stake on the East side of the stone. Accepted the stake hole as the corner and reset the boulder over it. Set the long bolt on the West side of the stone, a short pipe on the S. side, and a spike on the East side. Set the concrete County Highway Department monument over the boulder and a 1/2" rod at the road surface. The corner is 1.0' West and .2' South of the location of the County Highway Department corner (removed).

9-30-1977 County Surveyor set a C.I.M. over the 1/2"x2' rod. RPs- corner 1.0 W and .2 S of the county highway department monument(removed),Corner 1/2' south centerline and in line with fence south, punch mark in top lug E and CMP in driveway south SSE 36.10, punch mark in top lug W end CMP in driveway south SSE 36.10, county highway department disc in pp# 40616 SW 61.34.

5-13-1998 County Surveyor found CIM in good condition. Referenced before cold recycling bituminous surface of CR #14.

8-18-1998 County Surveyor set P.K. Nail in new bituminous surface from 5-13-1998 reference.

5-25-1999 County Surveyor set 1" square pipe w/cap from ties.

3-7-2001 Mn/DOT Survey Crew found monument in good condition.

7-17-2003 County Surveyor found 1" square pipe w/cap at surface in good condition. Set 2 pts and tied out corner for Hwy 52 construction.

5-26-2005 County Surveyor set 5/8" copper plug w/punch mark at surface from 2003 tie out.

8-25-2011 County survey crew found copper plug with punch mark in good condition