Certificate of Location of Government Corner

ID#: 843306 **Description:** 1/4 SEC COR 32 33 84 **Date Set:** 8/23/2006 **County:** Olmsted

Section: 33 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 85' west of centerline of SBL of TH 52 at Sta. 2009 + 12
County highway disk up 2' in S side 15" Maple W 27.4' (slope)
County highway disk up 6' in NW side 15" Cottonwood NE 40.61' (slope)
Post w/sign 2' west
This corner is located by GPS reference stations "Truck C & D"

Corner History:

5-1873 T. Hunter No. 227 pg. 224 Corner gone, set no corner.

5-1874 T. Hunter No. 250 pg. 249 Set temp. point as the E. 1/4 corner at the mean meas. Of the East half of the N. lineof the Sec. And the East half of theS. Lineof the section. He also set temp. points on the E. 1/2 of the E-W 1/4 line for points to the South.

7-1-1902 R.Fraser Bk.10 Pg.50-51; Set boulder stone on N-S section line & 1/4 line run from west.

11-1912 D. Williams Bk. B pg. 186 Reset the corner by the notes form the survey by Hunter of 5-1874 pg. 249 Bk. A.

4-28-1972 County Surveyor set CIM over 3/4"x12" iron with original stone on west side CIM.

9-1977 Mn/DOT provided additonal RPs; 40D nail up 2.0' on ESE side twin maple SW 10.18, fence corner ENE 10', centerline South bound lane T.H.52 E 85'.

6-5-1985 County Surveyor took additional references before road construction destroyed corner. Took RPs-RM#1; 5/8" rod 12.2 ± east of east edge concrete on NBL T.H.52 and 3' ± Nly of center of 15" CMP under NBL, punch in lug at top east end CMP SE 7.01. RM #2- Mn/DOT BM T5508 point 1' west of BM sigh & post and 2 1/2' west of pipe corner post to fences N-S-E in N side 14" maple WSW 39.85 Mn/DOT R/W monu SW 100.99

1-2001 Mn/DOT Survey Crew found spike at coordinate position. (Corner and all ties were destroyed in T.H. 52 construction).

6-25-2001 Mn/DOT Survey Crew set a 2"x2"x30" square pipe with cast iron cap at coordinate position.

10-2-2002 Mn/DOT Survey Crew found monument in good condition and took new ties.

1-21-2003 County Surveyor found 2" square pipe with Mn/DOT Cast Iron Cap in good condition at surface.

7-10-2006 County Surveyor did not find any monument but did find sign. Both ref. pts. set in '03 are gone. Set new ref. Pts.

8-23-2006 County Surveyor set 6' telspar w/CIC from computed coordinates up 0.3'. Set sign & post 2.0' west. Did not check ties, because of new Mn/DOT R/W fence.