Certificate of Location of Government Corner

ID#: 843504 **Description:** S 1/4 SEC COR 35 84 **Date Set:** 6/11/1993 **County:** Olmsted

Section: 35 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 28 1/2' south of centerline of CSAH 14 on curve and 74 1/2' west of centerline of driveway south
Spud in PP #33678 SE 108.25'
This corner is located by GPS measurement

Corner History:

6-1900 Robert Fraser Pg.649 No.582; Corner gone, set boulder stone 6x6x10 M & L 39.68

1938 county highway department 1/2" pipe in blacktop, spud in pp SE 92.0, 1/2" rod S 33.0, triple burr oak S 53.0, 18" burr oak SE 81.5.

8-1958 John Jerr, County Surveyor found references in stumps of trees marked in 1938. Drove 1/2" pipe thru blacktop as 1/4 corner.

1965 RPs- Now 1" pipe Bk.310, disc in pp NE 79.33, disc in pop SE 91.97

4-1979 County Surveyor found 1/2" pipe in centerline road and 10' east of fence north & south.

10-1992 County Surveyor set 1/2" iron @ 60d spike set by county highway department set from transit ties. county highway department set CIC/p squared over 1/2" rod. Corner falls 4' southerly if shoulder edge of CR# 14 on curve. RPs- centerline CR# 14 on curve north 28 1/2', spud in pp# 33678 SE 108.25, centerline driveway south, east 74 1/2'.

6-11-1993 County Surveyor set telspar pipe w/cast iron cap as corner south shoulder of CR #14 @ sod line.

1-15-2004 County Surveyor found cast iron cap on telspar pipe down 0.7' in good condition.