Certificate of Location of Government Corner

ID#: 843506 **Description:** 1/4 SEC COR 34 35 84 **Date Set:** 7/22/2004 **County:** Olmsted

Section: 35 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of centerline of N-S twp road
60d spk nearly grown over in W side huge Maple NNE 73.31'
Center 7" Pine ENE 71.0'
Nail in knot in S side TP ENE 27.95'
Spud in S side PP #33632 W 32.06'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick, Deputy Surveyor North between sections 34 and 35. 40.00 chs. Set quarter section post in mound with trench and pits and charred stake and planted Osage Orange seeds N.E. and S.W.

10-1913 David Williams (P. 240B), County Surveyor, used corner to set center Sec. 34 and 1/16 corner West.

8-1960 John Kerr (B80 P.46), County Surveyor, established corner by using center 34 and line of fence West. Corner not set.

9-1966 John Kerr (B.94 P.65) set 1" iron midway and on line.

4-26-1972 County Surveyor found 1/16 stone West set by Williams in 1913. Ran line from W. 1/4 Cor. 34 over center and doubled measure to 1/16 found. Dug at this location but found old road gone to clay. Point fell 16.3' South and 2.8' East of Kerr's 1" iron. Removed iron and reset it at the new point. East-West 1/4 line is now straight.

6-12-1974 County Surveyor reset C.I.M. over 1/2" x 2' rod. RPs-Correct corner lies 16.3' South and 2.8' East of John Kerr's 1966 location.

7-22-2004 County Surveyor found CIM down 0.6' leaning south. Took local ties and removed. Found 1/2" iron rod down 2.6' in good condition. Set 4 1/2' cast iron cap on telspar pipe down 0.5' over rod. Tie in pp is blocked by a TCM box.

10-3-2005 County Surveyor found telspar pipe w/CIC in good condition down 0.45'. Did not check any ties.