Certificate of Location of Government Corner

ID#: 850104 **Description:** 1/4 SEC COR 1 12 85 **Date Set:** 10/26/1977 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in a pasture
This corner is located by GPS measurement

Corner History:

6-12-1854 Gov't Notes: Cushing, Deputy Surveyor; West on true line between sections 1 & 12. 39.635 chs set quarter section post. Raised mount with trench and charred stake 79.27 chs. Section corner.

5-15-1877 Thomas Hunter, County Surveyor, (Pg.309 No.303) found an old stake that Mr. Smith, an old settler, averred to be the original corner, Set a boulder 8"x10"x17".

5-6-1898 William Fraser, County Surveyor, (Pg.629 No.569) found the boulder set Pg.309. Set the 1/16 east and the center 12 and the south 1/4 corner 12.

6-3-1902 Charles Armstrong, County Surveyor, (Pg.54B) found a boulder stone as the corner. Armstrong's measurements indicate that this corner is well north of a straight line between the section corners.

10-19-1960 J. Kerr, County Surveyor (B82 Pg.11) records a 3/4" pipe 6' long with rocks piled around it as the corner 1.75 south and 3.9 west of the fence corner. (Kerr's notes do not state whether this corner was set or found. However, Kerr's measurement east fits Fraser's closely and he shows the corner on the N-S 1/4 line of section 12 where he found Fraser's center 12 and had reset the S 1/4 corner 12 according to Fraser' survey. He also shows the corner 18' north of a straight line agreeing with Armstrong.)

7-3-1964 John Kerr set a CIM over a 1"x30" pipe at the location of the 3/4" pipe recorded in 1960.

5-21-1975 County Surveyor used this corner to set 1/4 corner 1-2.

10-26-1977 County Surveyor found that the old fence line had been graded out and the entire area now cultivated. Found the 1" pipe that Kerr had set beneath his CIM over the pipe. Set CIM over the 1" pipe below the plow line.

6-29-2001 County Surveyor found CIM in good condition. Set post 2 ±/ - East. Located its position using GPS.

1-30-2003 County Surveyor found CIM in good condition down 0.9'. Set sign & post 2.0' NE.

4-13-2011 Mike Hendrickson, MNDOT, found cast iron monument down 1'. Left monument as found. Measured the following reference tie: Benchmark disk 5508 F - 704.25 Southwest

8-15-2011 Jeff Harcey, MNDOT Crew Chief, found CIM in good condition. Set additional ties as follows: 1/2" rebar, down 0.5', Az=21 degrees 22 minutes, 88.00'
1/2" rebar, down 0.5', Az=53 degrees 09 minutes, 98.27'