Certificate of Location of Government Corner

ID#: 850108 **Description:** N 1/4 SEC COR 1 85 **Date Set:** 10/08/09 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The cast iron cap is down 0.45'
The corner falls 2' north of centerline of E-W twp road and 45' west of driveway north
Disc with nail in W side PP S 29.84
This corner is located by GPS measurement

Corner History:

6-1902 Charles Armstrong (P54B), county surveyor states corner gone. Set 6"x10"x16" limestone midway and on line.

6 & 7-1969 John Kerr, County Surveyor dug, but found nothing. Set CIM midway and on line.

5-19-1975 Roger Brand, County Surveyor, after finding the correct corner at north section corner 1-2, dug midway and on line. Found nothing.

5-20-1975 Roger Brand, County Surveyor set CIM over 5/8"x12" rod midway and on line. Corner lies 1.7' north and 2.9' east of Kerr's CIM. Removed John Kerr's CIM.

6-29-2001 County survey crew found CIM in good condition.

10-08-2009 Joel Thoreson, County Surveyor computed a new corner location on the standard parallel by intersecting the n-s quarter line of section 1 with the south line of section 36-109-15. County survey crew set a cast iron cap on telspar pipe at the new corner location which is 1.47' south of the existing CIM. Removed the existing CIM.

2-26-2010 Rudy Martin, MN/DOT Crew Chief, found CIC on Telspar pipe in good condition.