Certificate of Location of Government Corner

ID#: 850407 **Description:** N SEC COR 4 5 85 **Date Set:** 1/11/01 **County:** Olmsted

Section: 04 **Township:** 108N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 10 1/2' NNE of centerline of twp road on curve
County Survey Disk in W side PP #35 N 31.42'
County Survey Disk in CP WNW 118.38'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: John W. Cushing, Deputy Surveyor; North on true line between sections 4 & 5. 81.0 chs. Intersect standard parallel 10.25 chs. East of post on the south line of section 32 in Twp 109 Range 15 west. Set post for corner to sections 4 & 5 C.C.. Raised mound with trench and pits as per instructions. Drove charred stake.

5-1899 Thomas Fraser (Pg. 428 No.416, County Surveyor found a stake in line with the fence running south. Set a stake as the N 1/4 corner section 5 midway and on line from the NW corner section 5 to the NE corner section 5.

11-1937 A.C. Leonard (Pg.473B) could not find the corner. Set a stake on line from a stone found at the N 1/4 corner section 5 to a stone from the stone at the N 1/4 corner section 4 and at Thomas Fraser's measure from the stone at the N 1/4 corner section 5. This stake also came in line with the old fence running south.

1966 John Kerr (Bk.94 Pg.47), County Surveyor used the line of a fence south as the E-W location of this corner in setting the N 1/4 corner section 5.

9-16-1976 County Surveyor dug for this corner with the backhoe and found no evidence of the corner.

9-21-1976 County Surveyor set CIM over a 1/2"x2' rod as the corner on line from an iron found at the S 1/4 corner section 32 T109N, R15W, to the CIM at the N 1/4 corner section 4, T108N,R15W, and at Gov't measure from the south 1/4 corner section 32. This corner came approx. 25' west fo the fence south. We believe this fence is not in the same location it was during Fraser's and Leonard's surveys.

11-25-1981 County Surveyor removed CIM and iron beneath set in 1975 and reset CIM over 1/2"x25" rerod, .33 north to be on line from the south 1/4 corner 32 109-15 to south section corner 32-33, 109-15 as set this curvey and at Gov't measure (676.50) from south 1/4 corner 32, 109-15. The corner is 3 1/2' west of center of field drive south and 1 1/2' north of centerline E-W-road. RPs- CSD in east side pp #35 NNE 31.59,CSD in south side corner post to fence north WNW 118.38.

9-11-1985 County Surveyor found CIM ok.

9-18-1991 County Surveyor tied out CIM for road construction. RPs-CSD in pp north 37.05, SE corner block found NW 54.93

1-8-2001 County Surveyor found 1/2" pipe w/plastic cap down 0.7' in good condition.

1-11-2001 County Surveyor removed 1/2" pipe w/plastic cap and set 1" square pipe w/cap at surface from 1991 tie out.