Certificate of Location of Government Corner

ID#: 850605 **Description:** W SEC COR 6 7 85 **Date Set:** 2/22/2006 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: Ball, Deputy Surveyor; North between Section 7 & 12 63.50 Creek 50 links wide runs east. 68.20 14" elm. 80.0 set corner post. RPs- 14" elm S1W 212 links, 10" aspen N65W 20 links, 10" cherry S9E 28 links, 10" box elder N17E 16 links.

9-1882 T. Hunter Pg.379 No.370; Corner missing, SE bearing tree standing and stumps of NE and NW bearing trees. Reset corner with short stake driven even with surface. Measured east and set stake at 19.52 to S 1/4 6, a corner reset by bearing trees.

11-2-1971 County Surveyor set 3.5' piece fence post as corner on line from east.

6-24-1988 Vince Fangman set 5/8" rod over post with Dodge County aluminum cap. RPs- 16 d spike in SW face of railroad tie fence post ESE 11.70', 20d spike in 24" tree stump WSW 31.41', steel post as guard 1.0'south

3-25-2005 County Surveyor found monument in good condition down 1.2', removed Dodge County cap but left 5/8" rod. Set 5' telspar w/CIC over rod up 0.5'. All old ties are gone, nothing near enough to tie out to. Monument falls NE of intersection of old fences running south and west, both fences mostly gone.

2-22-2006 County Surveyor found telspar pipe w/CIC bent SE. Dug down and removed where pipe was straight. Set 6' telspar pipe w/CIC in existing hole from old pipe down 1.2'. Set sign and post 2.0' south.