Certificate of Location of Government Corner

ID#: 851305 **Description:** SEC COR 13 14 23 24 85 **Date Set:** 9/13/2005 **County:** Olmsted

Section: 13 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' SW of CP for fences N-S-W
Post w/sign 2' east
This corner is located by GPS reference stations "Titus A & B"

Corner History:

8-10-1854 Gov't Notes: John Cushing, Dept. Surveyor, 80.00 chs set post to corner of sec 13-14-23-24. Raised mound with trench as per instruction drove charred stake.

1-1892 Thos Fraser (P.468 No.450) corner gone could find no evidence or knowledge except the old fence south was set from original corner. Run line from 1/4 13-14 to SW 24 and set iron rod as corner 1/3 distance 39.78-1/3 2625.7 and in line fence south as lines E&W worst in county. This brought N-S line in line of fence west also claimed set from original corner. 16 south set stake M&L 19.89-1/6 which came 5' into river, took 12" black ash S45°E 15 lks as BT.

12-1894 W. Fraser (P.557 No.513) used corner set P.468 to run line west to S 1/4 15 to set SW cor 14. 40.24-5/6 2656.4 each half mile.

4-1903 Ch. Armstrong (P.49B) used corner fence post. 16 north stake M&L 19.92-1/2 1315.05'. 16 east stake M&L 19.94 1316 line east rough.

6-1947 J. Kerr (B.34 P.40) run line from SW 14 east. Set 3/4" square bar at 660' then axle shaft at 39.76.63' or 3/4 across S line 14. Found small L.S. on top of larger L.S. more than 1' deep at SE 14. Set well point with 1-1/4 pipe riser on top. Total mile 5302.5 (W. Fraser 5312.8').

10-1985 County Surveyor found 1-1/4" pipe set by Kerr. Pipe on west side of newer corner post (set in concrete) to fence N-S-W. Pipe into west edge of concrete and post being pulled down on west side of pipe to well point where pipe still straight and took shot there. Cant replace pipe without removeing corner post. Surveyor should not use top of pipe. There is an older post standing 1-1/2'± north of pipe.

10-29-1985 County Surveyor found 5/8"x12" sq headed bolt standing 2.64 N and 1.64 E of Kerr's corner and 2' E and 1/2' N of old C.P. (and down 6") probably T. Fraser's corner.

1-29-2003 County Surveyor found square bridge bolt in good condition down 1.2'. Bolt falls 2.0' East of N-S fence and 2.6' North of fence running West.

9-6-2005 County Surveyor found square bridge bolt and removed. Found 1 1/4" pipe on west side of corner post now leaning west along with corner post. Corner post will need to be pulled and replaced after corner is set.

9-13-2005 County Surveyor removed pipe and corner post. Reset corner post and set 6' telspar w/CIC up 0.6' from computed coordinates. Monument falls 0.86' SW of center of corner post for fences N-S-W. Set sign and post 2.0' east.