Certificate of Location of Government Corner

ID#: 851404 **Description:** 1/4 SEC COR 14 23 85 **Date Set:** 7/1/2003 **County:** Olmsted

Section: 14 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.1'
The corner falls 17' west of fence south, in line with fence north and 22' south of centerline of Riverheights Court
3/4" pipe on 1/4 line S 66.00'
3/4" pipe NE 92.81'
Post w/sign 2' South
This corner is located by GPS measurement

Corner History:

6-12-1854 Gov't Notes: Cushing, Dept. Surveyor, west on true line between 14 and 23. 40.00 set quarter section post. Aspen 10 in. N56W 30 lks. Aspen 30 in. S56W 23 lks. 80.00 section corner.

12-1894 W. Fraser (P.557 No.513) located temp point midway on section line for line north. Midway would be 40.24-5/6 2656.4' no meas north as corner not placed on line.

1947 J. Kerr (B.34 P.40) ran south section line SW 14 east 5302.5 R5312.8. Set 3/4" square bar at 660'. Set axle shaft at 3976.68'. Found stone small LS on top of larger LS below at SE 14. Set old well point with 1-1/4 pipe riser at SE 14. Did not locate or set perm corner at 1/4 14-23 apparently no river crossing in area.

3-1973 McGhie & Betts Inc., found iron shaft in place, possibly by J. Kerr, as they also found several irons along the sec line, left corner in place.

12-14-1990 Vince Fangman found 1" PTO shaft leaning, hit in recent grading. Adjusted up, reset a disc blade with 8" hole in center around monu. Set fiberglass post. RP's: 30d spk in 10" elm ESE 12.06', 3/4" pipe north on 1/4 line 66.00', 30d spk in 10" chinese elm WSW 12.50', 3/4" pipe NE 92.81'.

1-22-2003 County Surveyor found P.T.O. shaft down 0.2' in good condition.

7-1-2003 County Surveyor removed PTO shaft and set cast iron cap on telspar pipe down 0.2'.

3-15-2012 County survey crew found cast iron cap in good condition.